

B.M. 100.04 1/2" Spike in E. Pole 1971 S. of Iron N.E. Cor. Handley & Maxwell
 B.M. 100.58 SW cor conc. patch Ho #2446 S. Handley.

NOTE TO FIELD ENGINEER: If drives are constructed on U.S. Maxwell, check settlement of sewer ditch to determine if extra steel will be needed in the drives.

