

306' VCP/CIPP

Harrison

956

1919

957

956

Remove 301 If of 8" Pipe  
Install 301 If of 8" Pipe

MH 5348-018  
Remove Manhole  
Construct Shallow Manhole (4')  
Approx MH depth = 4.7 ft

(unpaved alley)

301'

MH 5348-015  
Approx MH depth = 3.9 ft

Estimated 11 Service Reconnections (4")

Sims Park  
Golf Course

925

Amidon

Perry

Coolidge

N

301'

900

901

902

Franklin

**SITE 3**

W HARRISON AVE

956

1919

957

956

N AMIDON AVE

N PERRY AVE

924

925



## Video Inspection Master Report

7/5/2012  
1:05 PM

US Structure: 5348-018      1919 W HARRISON ST      Date Insp: 6/7/2010      Basin: C03E  
 DS Structure: 5348-015      932 N AMIDON ST      Dir Televised: Upstream To Downstream

Pipe Information  
 Dia: 8      Material: VCP      Length: 301.1      Slope: 0.400      DVD #0585

Obs. #	VTR Counter	Distance	Location	Description	Rating	Obsrvd (gpm)	Est. (gpm)	Ratings		
								Struct	Clean	Remain (gpm)
1		0.0		5348-018 US Manhole	1	0.000		0	0	0.000
2		8.8		Crack-Radial	2	0.002		2	0	0.002
3		13.0		Wye Service	1	0.000		0	0	0.000
4		15.6		Wye Service	1	0.000		0	0	0.000
5		20.5		Sag	3	0.000		5	0	0.000
6		21.1	water on lens	Sag	1	0.000		1	0	0.000
7		24.5		Crack-Radial	3	0.004		5	0	0.004
8		26.4		Sag	3	0.000		5	0	0.000
9		27.3		Crack-Radial	2	0.002		2	0	0.002
10		31.4	water at top of lens	Sag	1	0.000		1	0	0.000
11		37.8	948 N AMIDON poor cond.	Break-In Conn	2	0.002		0	0	0.002
12		41.2		Wye Service	1	0.000		0	0	0.000
13		55.0		Roots	2	0.004		2	4	0.004
14		55.4		Crack-Radial	2	0.002		2	0	0.002
15		64.5		Wye Service	1	0.000		0	0	0.000
16		65.2		Broken Pipe	3	0.010		60	0	0.010
17		66.1	949 N PERRY	Break-In Conn	3	0.004		2	0	0.004
18		68.1		Crack-Radial	2	0.002		2	0	0.002
19		70.6		Crack-Radial	2	0.002		2	0	0.002
20		75.5		Broken Pipe	2	0.008		44	0	0.008
21		77.9		Broken Pipe	2	0.008		44	0	0.008
22		80.7		Crack-Radial	2	0.002		2	0	0.002
23		88.4		Broken Pipe	2	0.008		44	0	0.008
24		90.1		Wye Service	1	0.000		0	0	0.000
25		91.0		Crack-Radial	3	0.004		5	0	0.004
26		92.6		Wye Service	1	0.000		0	0	0.000
27		93.8		Crack-Horizontal	2	0.002		2	0	0.002
28		98.8		Broken Pipe	2	0.008		44	0	0.008
29		101.1		Crack-Radial	2	0.002		2	0	0.002
30		101.4	cracked	Observation Hole	1	0.000		0	0	0.000
31		103.5		Broken Pipe	4	0.030		78	0	0.030
32		106.3		Broken Pipe	2	0.008		44	0	0.008
33		113.7		Crack-Radial	2	0.002		2	0	0.002
34		114.5	942 N AMIDON	Wye Service	1	0.000		0	0	0.000
35		116.2		Broken Pipe	3	0.010		60	0	0.010
36		116.9	945 N PERRY / cavity forming	Break-In Conn	3	0.004		2	0	0.004
37		124.0		Crack-Radial	2	0.002		2	0	0.002

## Video Inspection Master Report

7/5/2012  
1:05 PM

US Structure:	5348-018	1919 W HARRISON ST	Date Insp:	6/7/2010	Basin:	C03E		
DS Structure:	5348-015	932 N AMIDON ST	Dir Televised:	Upstream To Downstream				
38	129.3		Crack-Radial	2	0.002	2	0	0.002
39	131.7		Crack-Radial	2	0.002	2	0	0.002
40	139.9	936 N AMIDON	roots / Wye Service	2	0.000	0	0	0.000
41	141.8		Crack-Radial	2	0.002	2	0	0.002
42	142.7	935 N PERRY / off the main	Wye Service	5	0.000	400	0	0.000
43	146.7		Crack-Radial	3	0.004	5	0	0.004
44	154.4		Broken Pipe	2	0.008	44	0	0.008
45	159.4		Crack-Radial	2	0.002	2	0	0.002
46	162.1		Crack-Radial	2	0.002	2	0	0.002
47	164.9		Broken Pipe	2	0.008	44	0	0.008
48	166.2	seal broken / roots	Wye Service	2	0.000	0	0	0.000
49	166.9		Broken Pipe	3	0.010	60	0	0.010
50	167.2		Broken Pipe	3	0.010	60	0	0.010
51	168.6		Wye Service	2	0.000	0	0	0.000
52	169.4		Broken Pipe	3	0.010	60	0	0.010
53	169.8		Broken Pipe	3	0.010	60	0	0.010
54	190.7	032 N AMIDON / poor cond.	Break-In Conn	3	0.004	2	0	0.004
55	194.1		Wye Service	1	0.000	0	0	0.000
56	195.3		Crack-Radial	2	0.002	2	0	0.002
57	198.3		Observation Hole	1	0.000	0	0	0.000
58	203.2		Crack-Radial	2	0.002	2	0	0.002
59	205.2		Crack-Horizontal	2	0.002	2	0	0.002
60	213.2		Crack-Radial	2	0.002	2	0	0.002
61	214.4		Wye Service	1	0.000	0	0	0.000
62	216.4	933 N PERRY	Wye Service	1	0.000	0	0	0.000
63	218.1		Crack-Horizontal	2	0.002	2	0	0.002
64	218.1		Crack-Radial	2	0.002	2	0	0.002
65	225.7		Crack-Radial	3	0.004	5	0	0.004
66	230.4		Broken Pipe	2	0.008	44	0	0.008
67	230.4		Crack-Radial	2	0.002	2	0	0.002
68	239.7		Wye Service	1	0.000	0	0	0.000
69	240.9		Broken Pipe	2	0.008	44	0	0.008
70	242.0		Wye Service	1	0.000	0	0	0.000
71	243.4		Crack-Radial	2	0.002	2	0	0.002
72	246.1		Crack-Radial	2	0.002	2	0	0.002
73	248.4		Crack-Horizontal	2	0.002	2	0	0.002
74	258.7	hole in side of pipe	Broken Pipe	4	0.030	78	0	0.030
75	264.8	924 N AMIDON	Wye Service	1	0.000	0	0	0.000
76	266.0		Broken Pipe	3	0.010	60	0	0.010
77	267.3	927 N PERRY	Wye Service / cracked	3	0.000	2	0	0.000
78	290.1		Wye Service	1	0.000	0	0	0.000
79	291.3		Crack-Radial	2	0.002	2	0	0.002
80	292.4	925 N PERRY	Wye Service / cracked	2	0.000	0	0	0.000
81	300.0		5348-015 DS Manhole	2	no recent inspection / fresh rock in alley			