

Install 500 lf of 8" Cured-in-Place Liner from MH 5647-024 to MH 5647-020

MH 5647-020


MH 5647-022  
Est. depth = 8.5 ft

MH 5647-023  
Abandon Manhole (in pavement)  
(line through manhole and abandon manhole over CIPP per City Spec)

MH 5647-024  
Est. depth = 7.0 ft

**SITE 7**







## Video Inspection Master Report

1/3/2013

2:50 PM

**US Structure:** 5647-024      **1818 E 3RD ST**      **Date Insp:** 9/18/2012      **Basin:** C03A  
**DS Structure:** 5647-023      **356 N KANSAS**      **Dir Televised:** Upstream To Downstream

**Pipe Information**

**Book & Page :** D-100      **Dia:** 8      **Material:** VCP

Obs. #	VTR Counter	Distance	Location	Description	Rating	Obsrvd (gpm)	Ratings			Remain (gpm)
							Est. (gpm)	Struct	Clean	
1		0.0	5647-024	US Manhole	1					
2		164.2	5647-023	(NO TAPS ON THE LINE) DS Manhole	1	(no elevation change in MH 5647-023)				

**US Structure:** 5647-023      **356 N KANSAS**      **Date Insp:** 9/18/2012      **Basin:** C03A  
**DS Structure:** 5647-022      **1717 E 3RD ST**      **Dir Televised:** Downstream To Upstream

Obs. #	VTR Counter	Distance	Location	Description	Rating	Obsrvd (gpm)	Ratings			Remain (gpm)
							Est. (gpm)	Struct	Clean	
1		0.0	5647-022	tv against the flow	1					
		0.0		PVC Begins						
		20.0	(approx distance)	PVC ends						
3		95.1	355 & 357 EAST 3RD STREET NORTH	South Wye Service						
2		166.9	5647-023	US Manhole	1					

**US Structure:** 5647-022      **1717 E 3RD ST**      **Date Insp:** 9/18/2012      **Basin:** C03A  
**DS Structure:** 5647-020      **388 N HYDRAULIC**      **Dir Televised:** Upstream To Downstream

Obs. #	VTR Counter	Distance	Location	Description	Rating	Obsrvd (gpm)	Ratings			Remain (gpm)
							Est. (gpm)	Struct	Clean	
1		0.0	5647-022	US Manhole	1					
2		17.7		Broken Pipe	3					
3		19.0		Broken Pipe	3					
4		62.7		Broken Pipe	3					
5		125.1		Broken Pipe	3					
6		163.9		Broken Pipe	4					
7		168.8	5647-020	DS Manhole	1					