

FEES

JEWETT

ROSS PARKWAY

# 4181

# 4021

MH # 5744-910  
Approx depth = 9.7 ft

MH # 5744-909  
Approx depth = 4.4 ft

# 4001

Remove 238 lf of 6" pipe and  
install 238 lf of 8" pipe


# 3949

238'

152'

183'

135'






ROSS PARKWAY

# 4001

# 4021

FEES

Aerial View



# Television Inspection Master Report

7/1/2003  
8:34:24AM

**US Manhole:** 5744-910  
**DS Manhole:** 5744-909

4005 E ROSS PKWY  
4025 E ROSS PKWY

**Date Insp:** 8/1/2000

**Basin:** C01A

**Dir Televised:** Upstream To Downstream

## Pipe Information

Shape:	Round	Length Status:	Project No.:
Dia/Ht	Width: 6 0	Material:	VCP
Length:	238.0	Slope:	1.000
Pipe Sec Length:	Comment:	Surface:	

## Inspection Information

Crew:	Percent Full:	Tape ID:	V-2448
Weather:	Purpose:	Counter Start:	
Surface Cond:	Flow:	Counter Stop:	
Dyed Test:			

### Maintenance Prior to TV:

Cleaned: 0	Degrease: 0	Point Repair: 0	Manhole Replace: 0
Root Cut: 0	Root Chem: 0	Other:	

Obs. #	VTR Counter Comment	Dist	Location	Description	Rating	Obsrvd (gpm)	Est. (gpm)	Ratings		
								Struct	Clean	Remain (gpm)
1		0.0	US Manhole	5744-910						
2		2.0	North	Wye Service						
3		37.0	North	Wye Service						
4		75.0	North	Wye Service						
5		85.0	South	Wye Service						
6		122.0	South	Break-In Conn						
7		149.0	Crown	Grease / Heavey grease						
8		167.0	Camera Blocked	Roots						

Roots & grease blocking the camera / cannot push past

Incomplete televising / no reverse setup done

**7-3**