



Note: Line 1 between MH #033 and 1st MH to the south on Armour was left as is, to act as an overflow out of MH #033. No new pipe installed.

