



- # 6971 - Tap - 18 Hampton Rd - 10-24-55
 - # 2009 - Tap - 11 Norfolk Dr - 4-23-48
 - # 1776 - Tap - 21 Huntington - 3-16-48
 - # 1777 - Tap - 23 " " " " 3-16-48
 - # 1778 - Tap - 25 " " " " " " " "
 - # 1779 - Tap - 27 " " " " " " " "
- Page 246 see reference
Douglas Conscience

SWR 2000-02026-9/13/00-Roto-Rooter-4" SCH40, CO RISER only- 1 Twinco, 2 Fernco to clay

NOTE: EASTBOROUGH
See title block on page 238
5971 - Tap 52A Norfolk - Ray - 11-13-57

Pump removed -
KELCO ST.
Abandoned 0+00 PUMP
See K-1287
10" V.C.R.

CONSTRUCTION RECORD

SERVICE RECORD

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS		
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East	
17+29.3	175.4	166.5	8.9	17+29.3									
18+0					17+99.0								
19+0	176.4	166.9	9.5	18+38.0	18+01.6								
20+0	177.6	167.5	10.1	19+59.0	18+91.6			2031-249559	#33	Mission	8-1-46	5-20-75	
21+0					20+35.9	20+38.4							
22+0	178.6	169.1	9.5	21+24.7									
23+0	180.4	170.7	9.7	22+18.0	Tap			#3005	#31	161 folk		11-6-50	
24+0					23+58.5	23+60.8							
25+0					24+56	24+58.5			#5189	#3	Hampton		3-8-51
26+0					25+88.3	25+90.8							
27+0	183.9	173.2	10.8	26+47.8	WEST	EAST			#2290	#23	Hampton		10-31-49
28+0					26+81.5	26+83			CONN. in M.H.	#1	St. James		(repair) 5-15-67
29+0					27+95.5	27+98.0							
30+0					29+16.2	29+18.7							
31+0					30+39.1	30+41.6							
32+0					31+67	31+69.5			23586	#1	Conn. for Hampton		7-24-89
33+0					33+15.0	33+17.5							
0+0	181.8	173.82	8.0	33+58.4	Tap			#1580	#14	St. James		6-11-52	
1+0					0+00=4+6.3 in line 3-B	NORTH	SOUTH						
2+0					0+47.1	0+49.6			#4164	#19	Douglas		3-22-51
3+0					1+17.0	1+19.5			8168	#21	Huntington		5-17-83
4+0					1+51.9	1+53.4			8089	#20	Huntington		5-6-83
5+0					2+52.8	2+55.3			#5990	#20	Douglas		7-29-53
6+0					3+47.9	3+50.4			#384	#17	Huntington		3-17-52
7+0	175.1	166.6	8.5	4+37.5	Tap								
8+0					5+54.4	5+56.9			#209	Lot 3 Blk. K	#14		8-23-48
9+0					6+63.5	6+66.0			#254	#21	Huntington		2-26-53
10+0					9+15.1	9+17.6							
11+0					10+21.5	10+24.0							
12+0					11+91.1	11+93.6			#2076	#5	Huntington		10-17-49
0+0	180.9	172.3	8.6	12+71.5	Tap								
1+0					0+27.2	0+29.7			#900	#17	Douglas		10-10-47
2+0					1+14	1+16.5			#1067	Lot 1 Blk. E	#15		11-4-47
3+0	173.0	162.9	10.0	1+28	Tap								
0+0					0+32.8	0+35.3			#4451	#6	Park		3-14-53
1+0									#3013	#16	Huntington		2-6-51
0+0					0+32.8	0+35.3			B3842	#32	Mission		7-22-65

NOTE: This project continues on page 247.

R-2000-00780-6 E. DOUGLAS-3/31/00-McClung's-TAP-76.6' E of PL (126.6 E of MH 12+71.5)(11+44.9)

SWR 2004 0910 4/6/04 #14 N. ST James - Mies Const (Repair permit to
repl under prop. post)