



### CONSTRUCTION RECORD

### SERVICE RECORD

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
<b>LAT. 3 SUB 5 S.S. 22</b>												
0+00	152.9	137.92	15.0	Existing M.H.								
					0+38°		7811		8134 LEVITT			8-19-58
					0+97°		7812		8138 LEVITT			8-19-58
1+00	151.8	138.32	13.5									
					1+64°		973607					3-13-57
2+00	149.6	138.72	10.9									
					+31°		10774		8200 LEVITT			1-2-59
					+88°		10133		8210 LEVITT			4-21-59
3+00	148.01											
	147.8	139.13 OUT 8.7 139.34 IN 8.3		3+01 <sup>5</sup>	Y WEST	Y EAST			1002 Blackwell	1001 Wicker		11-25-58
					+75°	+73°	8690	10554				6-4-59
4+00	150.3	140.83	9.5									
					+52°	+50°	8989		1006 Blackwell			1-6-58
5+00	153.7	142.23	11.5									
					+28°	+18°	10980	14934	1010 Blackwell	1013 Wicker		7-12-60
		143.13 OUT 12.1 146.50 IN 8.7		5+64°								11-13-61
6+00	155.2	146.85	8.4									
					+90°			13487		1021 Wicker		11-3-60
					+23°							
					+50°			14195		1029 B Wicker		5-16-61
7+00	158.3	147.85	10.4									
					1/4" PVC 40		945907		1018 R	1029 Wicker	1-14-74	7-29-59
					+192°	+172°	2016	10246	1037 B	1037 B	8-25-54	1-29-80
					+82°	+80°			Blackwell	Wicker	9-10-51	5-11-59
8+00	160.96	148.85 OUT 12.1 149.80 IN 11.2		8+01 <sup>3</sup>								
					+50°	8+48°	10457	18006	1026 Blackwell	1027 R		4-1-57
								10832	Blackwell	Wicker		7-4-59
9+00	167.4	150.80	16.6									
				Predco 4" SCH 40 9716	CITY REPAIR		2001-00413	21037	1030 R	1041 B	2-26-01	7-8-88
					+19°	+17°	8913	9662	Blackwell	Wicker	12-5-58	3-23-59
					+83°	+81°	7980	9663	Blackwell	Wicker	8-29-58	3-23-59
								93-5217-R				3-11-82
10+00	164.3	151.80	12.5									
					+52°	10+50°	15440		1038 Blackwell			4-6-62
	164.2	152.40	11.8	10+60 <sup>5</sup>								
<b>LAT. 10 SUB. 13 S.S. 22</b>												
0+00	118.4	112.79	5.6	Existing M.H.								
	118.9	112.94	6.0	0+74°								
1+00	118.4	112.99	5.4									
					+63°	+20°						
								7902	1588 N. Clarence			8-20-54
2+00	118.3	113.19	5.1									
					+14°	+13°	10299		1580 N. Clarence			3-22-60
					+87°	+85°	10172		1572 N. Clarence			4-28-59
3+00	118.2	113.39	4.8									
	118.5	113.49	5.0	3+50								
					+60°	+58°	7924		1562 N. Clarence			7-21-58
4+00	118.8	113.59	5.2									
					+56°	+58°	075748		1536 N. Clarence			12-12-79
							7903					7-20-51
5+00	120.0	113.79	6.2									
					+36°	+38°	075744		1548 N. Clarence			12-17-79
					+99°		16008		1570 N.R. Clarence			8-5-63
6+00	121.6	113.99	7.6									
	120.6	114.09	6.5	6+51°								
					+91°	+99°	7914	B5989	1593 N. Clarence	1460 N. Clarence		7-12-66
7+00	119.8	114.19	5.6									
					+69°	+71°	8326	B5988	1524 N. Clarence	1450 N. Clarence		8-20-58
8+00	119.4	114.39	5.0									
					8+43°	+45°	8505		1516 N. Clarence			10-27-58
					+81°	+83°	10606		1508 N. Clarence			6-11-59
9+00	120.8	114.59	6.2									
	120.9	114.65	6.2	9+30°								
					+357	+377						
					+97°	+99°	4803	7877	1480 N. Clarence			9-5-58
10+00	120.5	114.79	5.7									
					+69°	+71°						
11+00	121.3	114.99	6.3									
					(11+39)	+73°		B5891		1410 N. Clarence		6-23-66
	120.6	115.16	5.4	11+83°								

2001-00413-212601-10305 Blackwell-Redde Root-4" Predco-CITY REPAIR-144'N of MH 10160.5(9716) ITWINCO, 1022, 11422, 2V45, Fernco to CI @ house

8924 Top 1014 Blackwell Richard Top No. 1-7-59 5196

10134 Top 1005 Wicker Eugene Perdie 4-22-59 4142.5

82010 Top 8115 E Zimmery Philip 6-23-59 10135

B1846 Top -2021 W. 15th St - Dorothy Roy 8-27-64 - 1456

B5982 - 14140 N. Clarence - Bernice Zimm 6-23-60 (8+70)

B5987 Top -1430 N. Clarence - Monte Gillis 7-12-66 (9+72.0)