



LATERAL 19 S.S. 22
 PETER KENIT SONS CO. 8-22-58
 BK. NO. K-44 PROJ. NO. C25-70

2000-02499-10/15/00- 3220 50ak st
 Redi-rooter- 4"sch40- 4"WYC 95.1' S of
 MH 1+98.2 (2+93.3) - Replace entire line
 Existing co @ house - No alley - TWIN CO
 1V22

SUT-2001-02023- 8/15/01 233 S. West
 B+L FVC

ST.



1" = 80'

SILVER

33RD

ST. 50.

CONSTRUCTION RECORD

SERVICE RECORD

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North-West	South-East	North-West	South-East	North-West	South-East	North-West	South-East
Cont. LAT. 6 6+00	121.0	114.30	6.7	5+99°		6+11.1 +45°		66273		155 S. West		5-25-77
7+00	121.3	114.50	6.8		+78°		7998		156 S Colorado		9-4-58	
8+00	120.7	114.70	6.0		+66°	+15° 7+00.2	7898	10083 60910	144 S Colorado	139 S West	9-8-58	4-23-59 4-12-77
9+00	120.4 119.6	114.80 114.90	5.6 4.7	8+50° 4" stub E	+89° +133°	8+44° 8+33°	8033	84005 10282	136 S Colorado	123 S West	4-200 9-11-58	8-19-65 4-23-59
10+00	117.8	115.10	2.7		+86°	+55° +996	8019	8020 15072	130 S Colorado 122 S Colorado	113 S West	9-11-58	1-3-62
11+00	118.0	115.30	2.7		+79°	+177 +406	10926	14268	112 S Colorado	119 S West	7-16-59	
	118.1	115.36	2.7	11+27° 8" stub N.	+13°		10856	12719	107 S West	107 S West	7-13-59	5-2-60
LINE #5A 0+00	118.20	113.74	4.5	Existing M.H.	+44°	+42°	8190		222 Colorado		9-20-58	
1+00	118.5	113.94	4.6		+32°	+30°		175005 50 C5590 15601	233 S West	237 S West	10-22-79 6-14-76 5-8-62	
	118.5	114.02	4.5	1+39°								
LATERAL LINE #1 0+00	94.5	88.23	6.3	Existing M.H.	+09°	+11°	17383		715 W. 31st St.		7-10-63	
1+00	95.4	88.30	7.1									
2+00	95.0	88.40	6.6	1+98°								
3+00	94.8	88.50	6.3		+41°	+22°	15401		3212 S Oak		4-2-62	
4+00	95.0	88.60	6.4		+23°	+91°	208349		3230 S Oak		11-15-60	
5+00	94.8	88.65	6.2	7+50°	+62°	+60°	B4411		3222 S Oak		10-25-65	
6+00	94.8	88.70	6.1		+23°	+21°	15118		3236 S Oak		1-30-62	
7+00	94.8	88.80	6.4		+87°	+85°	15119		3244 S Oak		1-30-62	
8+00	94.8	88.80	6.4		+50°	+48°	13745		3252 S Oak		1-9-61	
9+00	94.8	88.90	5.9		+12°	+10°	13199		3260 S Oak		9-6-60	
10+00	94.8	88.90	5.9		+72°	+70°	8165		3302 S Oak		9-24-58	
11+00	94.9	88.95	5.0	7+51°	+29°	+45°	2248		3310 S Oak		12-81 9-24-58	9-7-82
12+00	94.8	89.00	5.8		+79°		8166		3315 S Oak		1-2-81	10-8-51
13+00	94.8	89.00	5.8		+29°	+55°	8167		3318 S Oak		9-24-58	
14+00	94.5	89.10	5.4		+94°		8304		3324 S Oak		10-3-58	3-17-59
15+00	94.5	89.10	5.4		+57°	+26°	8305		3327 S Oak		10-3-58	12-17-58
16+00	94.2	89.20	5.0	10+026°	+92°							
17+00	94.7	89.30	5.4		+183°	+177°			3342 S Oak		12-15-58	
18+00	94.7	89.30	5.4		+04°	+036°			3350 S Oak		7-22-75	
19+00	94.5	89.40	5.1		+41°				3357 S Oak		10-3-58	
20+00	94.9	89.45	5.4	12+506°	+82°	+50°			3366 S Oak		1-11-63	5/20/60
21+00	95.1	88.50	6.6	Existing M.H.	+28°	+30°			3374 S Oak		7-24-68	
22+00	95.2	88.65	6.5									
23+00	95.2	88.66	6.5	1+084° 4" stub N.W.								

8069 6" x 10" wye 3335 S Silver Denbury 9-22-59 9+92.1
 96-14607-2210 6" x 10" wye 3343 S Silver Denbury 10-10-58 10+53.6
 8231 Tap 3319 Silver Mt. Cay 10-10-58, 8+18.5
 22621 Tap 203 w. 31st St. ac. Leo. Duffin 1-8-65 tap (1469)
 M.C.#02 218 3310 S Oak 1-2-81 (Nancy) M.H. 7+51.0
 96-14798-794-96 3343 S Silver