



SCALE 1" = 200'

OUTFALL SEWER, MAIN A, LAT. A1, A2, A3, A4, A5,
 A6, A7, A8, A9; A10 - LAT. 5, 6, 7, 7A, 8, 8A.
 COUNTRY ACRES IMPROVEMENT DISTRICT
 FLOYD B. DEVLIN, ENGR. - UTILITY CONTRACTORS, INC.
 CONSTRUCTION DATE, 1955-BOOKED, 1962

NOTE:
 OUTFALL SEWER CONTINUES
 ON PAGE J181

BIRCH
 REDBARN
 MURDOCK

BEKMEYER LANE
 BROWN THRUSH
 SCHOOL

WOODCHUCK
 CHICKADEE
 QUAIL
 COTTONTAIL
 LANE

LANE
 AVE.
 AVE.
 AVE.
 LANE

Lot 5

Lot 6

Lot 7A

Lot 8A

R65-260

CONSTRUCTION RECORD						SERVICE RECORD						
STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
Lot A 9												
0+00	39.8	29.51	10.3	EXIST. 0+00								
1+00	39.9	29.91	10.0		4" x 45' 40' TAP		27177		920 N BEAUMTHER		3-1-91	
2+00	40.0	30.31	9.7					95-117287	925 COUNTRY ACRES			7.25-95
3+00	39.8	30.71	9.9									
	39.7	31.06	8.6	3+87 2								
4+00	39.7	31.11	8.6			9+33.10 TAP		11303	911 BERRYVIEW			6-27-84
5+00	39.6	31.51	8.1									
6+00	39.8	31.91	7.9									
7+00	40.0	32.31	7.7									
	39.8	32.60	7.2	7+73 2								
Lot A 10												
0+00	40.2	30.82	9.4	EXIST. 0+00								
1+00	40.3	31.22	9.1						9616407	925 N BEAUMTHER		9-23-96
2+00	40.4	31.62	8.8									
3+00	40.4	32.02	8.4					91-128067	705 N BEAUMTHER		10-10-97	
	40.5	32.37	8.1	3+87 2	4" x 40' 3" 5" STR 2 TAP			10193-7-01	863 BEAUMTHER		4-1-97	
4+00	40.6	32.42	8.2									
5+00	40.6	32.82	7.8									
6+00	40.7	33.22	7.5									
7+00	40.8	33.62	7.2									
	40.9	33.91	7.0	7+73 2				98-148737	800 RED BARK		8-12-98	

Note: For Location See Next Page (184)

Outfall Sewer

0+00	31.6	20.92	10.7	EXIST. 0+00								
1+00	32.1	21.22	10.9									
	32.4	21.31	11.1									
2+00	32.5	21.44	11.1		2+26 2							
3+00	32.8	21.56	11.2		3+10 3							
4+00	33.5	21.68	11.8									
5+00	34.5	21.80	12.7		5+6 3 3							
	34.6	21.82	12.7	5+18 2	4+70 2							
6+00	35.1	21.92	13.2		6+43							
7+00	34.3	22.04	12.3		7+25 4							
8+00	33.8	22.16	11.6									
	33.9	22.23	11.7	8+56 2	8+16							
9+00	34.0	22.28	11.7		9+78 2							
10+00	34.4	22.40	12.0		10+61 6							
11+00	34.4	22.52	11.9		11+44 2							
	34.4	22.61	11.8	11+92 2								

Continued On Next Page (184)

3106 416
 11-3-71 250° Spec Fee Per 11/27/71
 9-7-71 250° Spec Fee per 9/7/71
 5-18-72 250.00 Spec Fee per 4-3-72
 12-21-71 250.00 Spec Fee per 12-21-71
 6-16-70 250.00 Spec Fee per 6-16-70
 6-21-68 250.00 Spec Fee per 6-21-68
 5-9-73 250° Spec Fee 5-9-73
 5-9-73 250° Spec Fee 5-9-73
 7-30-73 250° Spec Fee
 7-30-73 250° Spec Fee

R2000-00189
 (974762-900 Braumthru) - 10-5-79 - Bluffs (3+93.0)
 # 71431 - 906 Braumthru - 4-26-79 (3+23.5) - R-16160 - McClung - 4" x 40 - Precko - 63.6' W of MH 3+87 (3+23.6)
 # 27166 - 212 7/91 - (920 Braumthru) - Bowers Aly (sto at s. tree in back yard)
 # 19359 - 4/1/91 - 863 N. Braumthru - Rep. Branny

CONSTRUCTION RECORD

SERVICE RECORD

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
<i>Outfall Sewer</i>												
	41.0	out 26.04 in 26.14	14.9 14.8	37+23 ⁷⁶								
38+00	41.1	26.23	14.9		38+34.56	38+03.75	2131	5965	8100 W Murdock	8112 W Murdock	12-17-80	6-7-82
39+00	41.2	26.35	14.8			39+84.56		15119				11-26-85
40+00	41.4	26.47	14.9					B5831			(38+33.36)	6-16-66
41+00	41.2	26.59	14.6					17241			(41+21.56)	6-10-63
	41.2	26.68	14.5	41+72 ⁵⁶				B1850			(41+62.56)	8-27-64
42+00	41.1	26.71	14.4									
43+00	41.1	26.83	14.3									
	41.2	26.89	14.2	43+49 ⁸⁶								
44+00	41.2	26.97	14.2									
45+00	41.1	27.13	14.0									
46+00	41.0	27.29	13.7									
47+00	40.8	27.45	13.2									
	40.8	27.58	13.2	47+72 ⁷⁶								
48+00	40.8	27.62	13.2									
49+00	41.0	27.78	13.2									
50+00	41.2	27.94	13.3									
	41.4	28.06	13.3	50+73 ⁶⁶								
51+00	41.5	28.10	13.4									
52+00	41.7	28.26	13.4									
53+00	41.7	28.42	13.3									
54+00	41.5	out 28.58 in 28.60	12.9 12.8									
	41.4	out 28.70 in 28.70	12.7	54+09 ⁴⁰								
55+00	41.3	28.84	12.5									
56+00	41.2	29.00	12.2									
	41.1	out 29.02 in 29.12	12.1 12.0	Exist. 56+13 ⁸⁰								
<i>Lat. 5</i>												
0+00	41.0	out 26.08 in 36.64	4.36	Exist. 0+00								
	41.2	36.98	4.2	0+85								5-28-91
												3-20-68
<i>Lat. 6</i>												
0+00	41.2	out 26.68 in 35.66	14.5 5.5	Exist. 0+00								
1+00	41.2	36.06	5.1									
	41.2	36.26	4.9	1+50								
<i>Lat. 7</i>												
0+00	41.0	34.64	6.4	Exist. 0+00								
	41.1	out 34.93 in 35.03	6.2 6.1	0+73								
1+00	41.2	35.14	6.1									
2+00	41.3	35.54	5.8									
3+00	41.5	35.94	5.6									
	41.6	out 36.03 in 36.13	5.2 5.1	3+24								
4+00	41.6	36.43	5.2									
5+00	41.8	36.83	5.0									
6+00	42.0	37.23	4.8									
	42.2	out 37.63 in 37.73	4.6 4.5	6+99								
	42.2	37.94	4.3	7+51								
<i>Lat. 7A</i>												
0+00	42.2	37.80	4.4	Exist. 0+00								
	41.9	38.02	3.9	0+55								

SWR 2000-01126 Selo 8016 W. School St. - Rep. Str 41+66 to 4" SCH 40 2-Way Clo installed
 Rep (4" x 8" x 17+01.2)
 95-9201-7 6-22-95 819 N Chickadee (large 1+01.2)
 014722 - Repair 735 Redbar - Stamp - 10-8-79 (5+76.8)
 068647 - Repair - 811 Chickadee (1+92.7) # 20819 - 12-28-90 - 819 Redbar N Jones
 074234 - Sewer - 7-13-79 Repair 811 Woodchuck
 SWR 2001-02551 101154 735 N Chickadee - Clearwater F.Y.

2001-01698-7/10/01- 940 Redbarn- Fadgett Ex- 4" SCH40b" Fredco 82.5' NW of MH 311 (CITY Repair) ITWIN CO, 2V33, 1V45
 (NO ORIGINAL CONNECTION INFO)

2005-03248-12/29/05-- 7800 W Cottontail - c/o 4" SCH40PVC, 4" @ house - American SWR

2001-03308- 946 N Country Acres- 12/28/01 Wichita Exc- Donut in wye 81' N of MH 0100 (0181) 1V22, 1TWINCO, 1 Fernco 4" 40 PVC

2000-02719- 975 N Denmark Ave- 12/14/00- Padgett Ex- 4" SCH40, Donut (Y was good) 2H22, 2H45

SWR2005-03144- 1001 Emerson- 2/17/02- Roto-Rooter- c/o- 4" SCH40 PVC, (1) Twinco

SWR2000-00584-R- 959 N Denmark Ave- Reddi Rootr- 3/6/00- 4" SCH40 - Tied to clay tile by Property Line- 2Twin co, 2H45. 1-4" Y

SWR2000-01019 4/26/00 1026 N ^{Red} COUNTRY ACRES - Always p/b - 4" SCH40 - 8' S of MH 1100 (1102)
1-Twin co, 1V45

2001-01211-5/17/01-1025 N Wilbur - Roto-Rooter - 4" SCH 40 - install 1 TWIN CO

Rep 2001-2004-1/2/01-Reddi Rootr - 4" SCH 40 - TWIN CO, 1 H 45 - Repair 7' from main

SWR 2002-02609 9/23/02 1209 N ^{Rep} EMERSON - Padgett AT:

SWR 2002-03095 11-13-02 1034 N ^{Rep} EMERSON - 4" sch 40 PVC - wye conn. at 171.6' N. of Mtl (city wye Rep) 1 Twin C.O.

SWR 2001-00404-907 Denmark-2/15/00 Reddi Ind - (2) joints, (1) twin c/o, shallow, c/o riser only

Repair 2000-00791- 3/28/00- 2844 N Wild Rose Ct - Roto - Install LTwin co 4" SCH 40 -

2000-00768 - 4/5/01 - 843 N Brownthrush - Aaah No leaks - 4" SCH 40 - tied to claytile 3' from main - ITWINCO, IV 22

SWR 2002 - 2/20/02 926 N Brownthrush - Paddett