



MH # 5746-074
Approx depth = 6.4 ft

Install 398 lf of 8"
Cured-in-Place Liner

MH # 5746-073
Approx depth = 8.9 ft

10-2

BAYLEY

BLUFFVIEW

BOSTON

Aerial View



Television Inspection Master Report

5/8/2007
8:26 AM

US Structure: 5746-074
DS Structure: 5746-073

910 S BLUFFVIEW ST
4210 E BOSTON ST

Date Insp: 4/5/2006
Dir Televised: Upstream To Downstream

Basin: EC01C

Pipe Information

Shape: Round Length Status: Project No.: I-003
Dia/Ht Width: 8 0 Material: VCP Index:
Length: 403.0 Slope: 0.037 Surface: Front Right-Of-Way

Inspection Information

Crew: 690 Percent Full: Tape ID: V-5974
Weather: Cloudy Purpose: TV Existing Line Counter Start:
Surface Cond: N/A Flow: Normal Flow Counter Stop:

Obs. #	VTR Counter	Distance	Location	Description	Rating	Obsrvd (gpm)	Est. (gpm)	Ratings Struct	Clean	Remain (gpm)
1	00	0.0	US Manhole	5746-074	1		0.000	0	0	0.000
2	2:42	60.8	East	Break-In Conn	1		0.001	0	0	0.001
			1004 S BLUFFVIEW							
3	3:35	93.7	East	Wye Service	1		0.000	0	0	0.000
			1004 S BLUFFVIEW							
4	5:30	170.0	East	Wye Service	1		0.000	0	0	0.000
			1012 S BLUFFVIEW							
5	5:51	177.0	Quad 1 / U-Rt	Broken Pipe	2		0.008	44	0	0.008
6	7:45	243.7	East	Wye Service	3		0.000	2	0	0.000
			1020 S BLUFFVIEW / FULL OF ROOTS							
7		284.0	East	Break-In Conn	1		0.001	0	0	0.001
			1026 S. Bluffview							
8	9:21	318.9	Quad 4 / U-Lt	Roots	3		0.008	5	8	0.008
9	9:30	322.1	Quad 1 / U-Rt	Roots	2		0.004	2	4	0.004
10	10:36	368.4	Joint	PVC PIPE STARTS						
11	11:18	376.3	East	Break-In Conn	1		0.001	0	0	0.001
			4210 E BOSTON / PVC							
12	12:00	393.0	DS Manhole	5746-073	1		0.000	0	0	0.000

Line has a lot of grease in it. Some small cracks and several places with roots at the joints.

10-3