



Figure 1
Typical Debris Pile
Approximately 14 piles are located on the site.



Figure 2
View of Typical Hedge Row to be removed.



Figure 3
View of Random Tree in Hedge Row




Figure 4
View of Random Tree in Hedge Row

File: L:\2018\18266039 - Cedar Creek Phase 1\Drawings\CD\Drainage\Demolition.dwg, Last Save: 5/20/2019 3:20 PM, Last saved by: CD Jurey
Last plotted by: Jurey, Caleb D., Plot Date: 5/20/2019 4:24 PM, Plotter used: None



© 2019 GARVER, LLC
THIS DOCUMENT, ALONG WITH THE IDEAS AND DESIGNS CONVEYED HEREIN, SHALL BE CONSIDERED INSTRUMENTS OF PROFESSIONAL SERVICE AND ARE PROPERTY OF GARVER, LLC. ANY USE, REPRODUCTION, OR DISTRIBUTION OF THIS DOCUMENT, ALONG WITH THE IDEAS AND DESIGN CONTAINED HEREIN, IS PROHIBITED UNLESS AUTHORIZED IN WRITING BY GARVER, LLC OR EXPLICITLY ALLOWED IN THE GOVERNING PROFESSIONAL SERVICES AGREEMENT FOR THIS WORK.



| REV. | DATE | DESCRIPTION | BY |
|------|------|-------------|----|
| | | | |
| | | | |
| | | | |



CITY OF WICHITA
WICHITA, KANSAS
CEDAR CREEK ADD,
PHASE 1

Demolition
Figures

JOB NO.: 18266039
DATE: March 2019
DESIGNED BY: CMB
DRAWN BY: CDJ

BAR IS ONE INCH ON ORIGINAL DRAWING
0 1" IF NOT ONE INCH ON THIS SHEET, ADJUST SCALES ACCORDINGLY.

DRAWING NUMBER

SHEET NUMBER **3A** OF **39**