

10TH


1057

PARKWOOD

RIDGEWOOD

1026

Aerial View



Television Inspection Master Report

5/2/2007
3:52 PM

US Structure: 5848-126
DS Structure: 5848-125

1057 RIDGEWOOD ST
1026 PARKWOOD LA

Date Insp: 1/17/2006
Dir Televised: Upstream To Downstream

Basin: E04H

Pipe Information

F-055

Shape: Round Length Status: Project No.:
Dia/Ht Width: 8 0 Material: VCP Index:
Length: 333.9 Slope: 0.400 Surface:

Inspection Information

Crew: 692 Percent Full: 10 Tape ID: 4992
Weather: Sunny Purpose: TV Existing Line Counter Start: 26.28
Surface Cond: Fences Flow: Normal Flow Counter Stop:

Obs. #	VTR Counter	Distance	Location	Description	Rating	Obsrvd (gpm)	Est. (gpm)	Ratings		
								Struct	Clean	Remain (gpm)
1		0.0	US Manhole	5848-126	1	0.000	0	0	0.000	
2		8.0	Joint	Roots	3	0.008	5	8	0.008	
3		12.0	Joint	Roots	2	0.004	2	4	0.004	
4		20.0	East	Wye Service	2	0.000	0	0	0.000	
5		22.0	West	Wye Service	2	0.000	0	0	0.000	
6		45.0	Joint	Roots	2	0.004	2	4	0.004	
7		76.0	East	Wye Service	2	0.000	0	0	0.000	
8		78.0	Joint	Roots	2	0.004	2	4	0.004	
9		79.0	West	Wye Service	1	0.000	0	0	0.000	
10		90.0	Joint	Roots	2	0.004	2	4	0.004	
11		138.0	Joint	Roots	3	0.008	5	8	0.008	
12		139.0	East	Wye Service	2	0.000	0	0	0.000	
13		142.0	West	Wye Service	2	0.000	0	0	0.000	
14		144.0	Joint	Roots	2	0.004	2	4	0.004	
15		205.0	East	Wye Service	2	0.000	0	0	0.000	
16		206.0	Quad 1 / U-Rt	Crack-Radial	3	0.004	5	0	0.004	
17		208.0	West	Wye Service	2	0.000	0	0	0.000	
18		233.0	Invert	Broken Pipe	3	0.010	60	0	0.010	
19		239.0	Crown	Broken Pipe	3	0.010	60	0	0.010	
20		252.0	East	Break-In Conn	1	0.001	0	0	0.001	
21		255.0	West	Wye Service	1	0.000	0	0	0.000	
22		262.0	Joint	Roots	2	0.004	2	4	0.004	
23		266.0	Crown	Broken Pipe	3	0.010	60	0	0.010	

Television Inspection Master Report

5/2/2007
3:52 PM

US Structure: 5848-126 1057 RIDGEWOOD ST Date Insp: 1/17/2006 Basin: E04H
DS Structure: 5848-125 1026 PARKWOOD LA Dir Televised: Upstream To Downstream

24	271.0	Crown	Crack-Horizontal	3	0.004	5	0	0.004
25	277.0	Joint	Roots	2	0.004	2	4	0.004
26	280.0	Joint	Roots	2	0.004	2	4	0.004
27	282.0	Crown	Broken Pipe	2	0.008	44	0	0.008
28	284.0	Crown	Broken Pipe	3	0.010	60	0	0.010
29	286.0	Joint	Roots	3	0.008	5	8	0.008
30	287.0	Crown / shifting pipe	Broken Pipe	3	0.010	60	0	0.010
31	289.0	Joint	Roots	4	0.010	10	25	0.010
32	291.0	Crown	Crack-Horizontal	3	0.004	5	0	0.004
33	292.0	Joint	Roots	3	0.008	5	8	0.008
34	293.0	Crown	Crack-Radial	3	0.004	5	0	0.004
35	295.0	Joint	Roots	3	0.008	5	8	0.008
36	300.0	Crown	Broken Pipe	3	0.010	60	0	0.010
37	301.0	Joint	Roots	3	0.008	5	8	0.008
38	304.0	Joint	Roots	2	0.004	2	4	0.004
39	305.0	Crown	Crack-Horizontal	3	0.004	5	0	0.004
40	307.0	Joint	Roots	2	0.004	2	4	0.004
41	308.0	Crown	Broken Pipe	4	0.030	78	0	0.030
42	310.0	Invert	Broken Pipe	4	0.030	78	0	0.030
43	318.0	East	Break-In Conn	3	0.004	2	0	0.004
1027 Ridgewood -								
44	321.0	West	Break-In Conn	2	0.002	0	0	0.002
1026 Parkwood - PVC								
45	322.0	Invert	Broken Pipe	3	0.010	60	0	0.010
46	325.0	Crown & Invert	Broken Pipe	4	0.030	78	0	0.030
47	329.0	DS Manhole	5848-125	1	0.000	0	0	0.000

Cracks are fairly bad from 282' to 318' but we will install CIPP instead of replacing the pipe