



Defect Listing Plot

Pipe Segment Refere... 14	City WICHITA	Street MCLEAN BLVD	Material PolyVinyl Chloride	Location C... Easement/R...	Sewer Use Stormwater
Upstream MH 0+44.08	Total Length	Up Rim to Invert 9	Shape Circular	Location Details LINE 0	
DS Manhole INVERT RIVER	Length surveyed 36.9	Down Rim to Invert 0	Height 18	Width 18	Pipe Joint...
SPR 0	MPR 0	PO Number 603 PPD 133119		Customer DONDLINGER	
SPRI 0	MPRI 0	Work Order		Purpose Pre-Acceptance	
QSR 0000	QMR 0000	Direction Downstream	Date 20200124	Media label	
OPR 0	Surveyed By Chuck	Pre-Cleaning Jetting	Time 12:13	Weather Light Rain	
OPRI 0	Certificate Number U-0118-070300421		End Time 12:16	Additional Info TV14	
	Date Cleaned 20200124				







Image Report 1/Page

Pipe Segment Refere... 14	City WICHITA	Street MCLEAN BLVD	Material PolyVinyl Chloride		Location C... Easement/R...	Sewer Use Stormwater
Upstream MH 0+44.08	Total Length	Up Rim to Invert 9	Shape Circular		Location Details LINE 0	
DS Manhole INVERT RIVER	Length surveyed 36.9	Down Rim to Invert 0	Height 18	Width 18	Pipe Joint...	




Distance:	0.0 ft.
Condition:	Access Point Manhole
Grade:	0
Remarks:	0+44.08



Image Report 1/Page

Pipe Segment Refere... 14	City WICHITA	Street MCLEAN BLVD	Material PolyVinyl Chloride		Location C... Easement/R...	Sewer Use Stormwater
Upstream MH 0+44.08	Total Length	Up Rim to Invert 9	Shape Circular		Location Details LINE 0	
DS Manhole INVERT RIVER	Length surveyed 36.9	Down Rim to Invert 0	Height 18	Width 18	Pipe Joint...	




Distance:	0.0 ft.
Condition:	Water Level
Grade:	0
Remarks:	N/A



Image Report 1/Page

Pipe Segment Refere... 14	City WICHITA	Street MCLEAN BLVD	Material PolyVinyl Chloride		Location C... Easement/R...	Sewer Use Stormwater
Upstream MH 0+44.08	Total Length	Up Rim to Invert 9	Shape Circular		Location Details LINE 0	
DS Manhole INVERT RIVER	Length surveyed 36.9	Down Rim to Invert 0	Height 18	Width 18	Pipe Joint...	




Distance:	15.7 ft.
Condition:	Water Level
Grade:	0
Remarks:	N/A



Image Report 1/Page

Pipe Segment Refere... 14	City WICHITA	Street MCLEAN BLVD	Material PolyVinyl Chloride		Location C... Easement/R...	Sewer Use Stormwater
Upstream MH 0+44.08	Total Length	Up Rim to Invert 9	Shape Circular		Location Details LINE 0	
DS Manhole INVERT RIVER	Length surveyed 36.9	Down Rim to Invert 0	Height 18	Width 18	Pipe Joint...	




Distance:	28.5 ft.
Condition:	Water Level
Grade:	0
Remarks:	N/A



Image Report 1/Page

Pipe Segment Refere... 14	City WICHITA	Street MCLEAN BLVD	Material PolyVinyl Chloride		Location C... Easement/R...	Sewer Use Stormwater
Upstream MH 0+44.08	Total Length	Up Rim to Invert 9	Shape Circular		Location Details LINE 0	
DS Manhole INVERT RIVER	Length surveyed 36.9	Down Rim to Invert 0	Height 18	Width 18	Pipe Joint...	



Distance:	36.9 ft.
Condition:	Survey Abandoned
Grade:	0
Remarks:	CAMERA UNDERWATER DUE TO RIVER LEVEL