
SHEET NO.	TOTAL SHEETS
21	33



BEAM REPAIR PLAN

Note:

1. For Concrete Repair Procedures See Sheet No. 22.

BRIDGE RAIL REPAIR

Type	No. Locations
A	15
B	2

Note: See Sheet 22 for repair details.

Legend

- Spalled and Deteriorated Sidewalk Floor Beam and Slab Areas to be Repaired.
- A — Type A Rail Repair
- B — Type B Rail Repair

No.	Revisions	By	Date
1			

CITY OF WICHITA, KANSAS
MICHAEL E. LINDEBAK, P.E.-CITY ENGINEER
MURDOCK BRIDGE
OVER LITTLE ARKANSAS RIVER
CONCRETE BEAM AND SLAB REPAIR
CITY OF WICHITA PROJECT NO. 472-82785

PROFESSIONAL ENGINEERING CONSULTANTS, P.A.
ENGINEERS
WICHITA, KANSAS

Designed by	R.A.S.	Checked by	R.A.S.
Drawn by	R.A.S./W.L.L.	Date October 1998	Job No. 96940

usr/ustn/dgn/1995/96940/beamfix.dgn
drawn by : ras/wll
plotted by : wll 12-29-98