

WL 1 - Sta. 0+66 - Sta. 0+78
Connection to previously HDD RJPVC Pipe
Looking West


PVC Restrained Joint
8" CIMJ 45° Bend
DICL Restrained Joint
8"x6" CIMJ Tee
WL 1 - Sta. 0+84 - Sta. 0+89
FH Tee Connection
Looking South


8"CIMJ 45° Bend
WL 1 - Sta. 0+89 - Sta. 1+37
8" Waterline & 15" RCP intersection
Looking South



WL 1 - Sta. 0+84
Fire Hydrant Assembly
Looking South