B.m. 82.97 = R.R. Spike E. face of Power Pole, N.W. cor. Seneca St. and 51st St. So. going west.

51st Street South

60 R/W

Seneca Street

Osage Avenue

Hazel Avenue

30' (min.) on Sec. Rd. R/W

Scale: Plan - 1" = 40
Profile - 1" = 5' vert.
1" = 40' horz.

Note: Tree removal shall be determined by Field Engineer. All trees which can be saved, shall be saved.

NOTE: CONTRACTOR SHALL GIVE PROPERTY OWNERS AFFECTED BY THE CONSTRUCTION OF THIS PROJECT A MINIMUM OF 24 HOURS ADVANCE NOTICE PRIOR TO THE START OF CONSTRUCTION.

Begin Project 0+00 Existing M.H. Sta 0+07 ± (Sta 0+00 Clay Study - Ref. (Sta 1s To Be Removed)

Iron, SW Cor. Sec. 20, TWP 28 S. R. 1 E.

50 L.F. Exist. Pipe to be Removed

8" Sewer Easement

Temporary Construction Easement

8' Utility Easement

Existing 8" Utility Easement

Unplatted

Tract 6 James D. Hurley 1769 Gold Dr.

Sta 1+01.3 Const. Std. M.H. Type 'A' or 'C'

Sta 2+59.1 Const. Std. M.H. Type 'A' or 'C' Sta 0+00 Line #2

Sta 5+50 Const. Std. M.H. Type 'A' or 'C'

Sta 8+35 Const. Std. M.H. Type 'A' or 'C'

Sta 10+00

Existing Ground

LINE #1

1002.7 L.F. of 8" A.B.S. Composite Pipe @ 0.13% Grade

As built 10-19-77

Lateral 17, Main 3, Southwest Interceptor
Between 51st Street So. and Hazel Avenue, from Seneca to E.L. Hankin 2nd Addition (approx. Osage & Hazel)
City of Wichita, Kansas
R. W. Linn, City Engineer
Date: June, 1977 Project Number: DBKL-576030

1/2 1/2

(6)

51st Street So.

N W E S

South Seneca Addition

Wilbur Darling 817 W. 31st St. So.
Wesley O. Ballinger 901 W. 31st St. So.
Carl O. Triplehorn 741 W. 31st St. So.

Seneca 2 | Gardens 3 | Second 4 | Addition

E. Benefit District

E & 8' Utility Easement

11+23 7
Sta 11+20 Const. Std. M.H. Type 'A' or 'C'.

8' Utility Easement

Sta 10+00

Sewer Easement

James W. Hurley 1705 Gold St. Tract 6

13+27 4
Sta 13+25.5 Const. Std. M.H. Type 'A' or 'C'. 8" stub E

8' Utility Easement

Tract 10 — Hankins 9 — V.L. Thomas 826 Hazel Ave. — 95'
Second 10 — A.L. Clark 818 Hazel Ave. — 95'
Addition 11 — Harold Staats 800 Hazel Ave. — 92.6'

Osage Avenue

Unplatted

Hazel Avenue

Sta 0+00 = Sta 2+59.1 Line #1

1 Hankins Second Addition

8' Utility Easement

1+24 9
Sta 1+24.0 Const. Std. M.H. Type 'A' or 'C'

Iron

20' Temporary Construction Easement

Sewer

1+72 4
Sta 1+71.8 Const. Std. M.H. Type 'A' or 'C' 6" stub SW.

Iron

Unplatted

South Seneca Gardens Second Addition

Leo C. Dearing 7337 S. Ida — Tract 2

Tract 1

Earl Scott 3614 So. Seneca

Unplatted

Hazel Avenue

33'

Slope

Section Line

Seneca Street

80'

N E S W

Scale
Plan 1" = 40'
Profile Vert. 1" = 5'
Horz. 1" = 40'

NOTE: Phone Mr. Earl Scott at 5214 S. Seneca, ph. # 582-1328, before Construction of San. Sewer for removal of Frame Bldg. at location of M.H.

Sta 10+00

Sta 11+20 Const. Std. M.H. Type 'A' or 'C'.

Sta 13+25.5 Const. Std. M.H. Type 'A' or 'C' 8" stub E.

Existing Ground

LINE # 1

76.95 | 77.10 | 77.13 | 77.85 | 77.80 | 77.48

325.5 L.F. of 8" A.B.S. Composite Pipe @ 1.5% Grade

10 11 12 13

85 80 75

Sta 0+00 = Sta 2+59.1 Line #1

Sta 1+24.9 Const. Std. M.H. Type 'A' or 'C'.

Sta 1+71.8 Const. Std. M.H. Type 'A' or 'C' 6" stub S.W.

LINE # 2

75.84 | 75.93 | 76.17 | 76.30

171.8 L.F. of 8" A.B.S. Composite Pipe @ 0.15% Grade

0 1 2

85 80 75

NOTE

CONDITIONS WERE MADE AS A RESULT OF RIGHT-OF-WAY ACQUISITION AND SHALL BE ADHERED TO BY THE CONTRACTOR AS FOLLOWS:

TRACT # 1 - CONTRACTOR TO RESET ANY FENCE IN SATISFACTORY CONDITION; ALSO TO REMOVE AND RESET METAL BUILDING.

TRACT # 2 - CONTRACTOR TO RESET FENCE, CLOTHESLINE POLES, AND PROTECT WELL; ALSO TO RESTORE ANY DAMAGED DRIVEWAY TO PRESENT CONDITION.

TRACT # 3 - IF PRESENT GRAVEL DRIVEWAY IS DAMAGED, CONTRACTOR IS TO RESTORE IN PRESENT CONDITION. CONTRACTOR IS TO REPLACE NORTH DRIVEWAY APPROACH TO ACCEPTABLE WIDTH AND MAY USE SUFFICIENT CULVERT TILE FROM SOUTH APPROACH TO DO SO.

TRACT # 4 - CONTRACTOR TO RESET FENCE.

TRACT # 5 - CONTRACTOR TO RESET ANY DAMAGED FENCE AND CLOTHESLINE POLES.

TRACT # 6 - CONTRACTOR TO RESET ANY DAMAGED FENCE.

TRACT # 7 - CONTRACTOR TO RESET ANY DAMAGED FENCE.

TRACT # 8 - CONTRACTOR TO RESET ANY DAMAGED FENCE.

TRACT # 9 - CONTRACTOR TO RESET ANY DAMAGED FENCE.

TRACT #10 - CONTRACTOR TO RESET ANY DAMAGED FENCE.

Lateral 17, Main 3, Southwest Interceptor
Line 1 continued & Line C
Project Number DBKL 376030

2/2 2/2

PLATE 1-SINGLE PLAN AND PROFILE FULL LINE
R. TELFORD NATIONAL TRACING SERVICE
INDIANAPOLIS, INDIANA

15 4 01 41