


NOTE:


If tamped backfill is not considered practical
do to condition of ditch, sandfill to the top
of pipe by the order of the City Engineer.



DETAIL OF
SPECIAL MANHOLE
Sta. 4+41



B.M. 131.80 "M" in Mueller Fire Hydrant N.W. Cor. Clifton
& Countryside Plaza.



Sanitary Sewer Grandview Heights Addn.
City of Wichita, Kansas
Private Job.

⑤

