

2+75.00

1395

1395

1390

1390

1385

1385

-70

-60

-50

-40

-30

-20

-10

0

10

20

30

40

50

60

70

1385

2+50.00

1395

1395

1390

1390

1385

1385

-70

-60

-50

-40

-30

-20

-10

0

10

20

30

40

50

60

70

1385

2+00.00

1395

1395

1390

1390

1385

1385

-70

-60

-50

-40

-30

-20

-10

0

10

20

30

40

50

60

70

1385

1+60.00

1395

1395

1390

1390

1385

1385

-70

-60

-50

-40

-30

-20

-10

0

10

20

30

40

50

60

70

1385

1+50.00

1390

1390

1385

1385

-70

-60

-50

-40

-30

-20

-10

0

10

20

30

40

50

60

70

1385

1+11.71

1390

1390

1385

1385

-70

-60

-50

-40

-30

-20

-10

0

10

20

30

40

50

60

70

1385

