

4+25.00

1395

1395

1390

1390

1385

1385

-70

-60

-50

-40

-30

-20

-10

0

10

20

30

40

50

60

70

4+00.00

1395

1395

1390

1390

1385

1385

-70

-60

-50

-40

-30

-20

-10

0

10

20

30

40

50

60

70

3+75.00

1395

1395

1390

1390

1385

1385

-70

-60

-50

-40

-30

-20

-10

0

10

20

30

40

50

60

70

3+50.00

1395

1395

1390

1390

1385

1385

-70

-60

-50

-40

-30

-20

-10

0

10

20

30

40

50

60

70

3+25.00

1395

1395

1390

1390

1385

1385

-70

-60

-50

-40

-30

-20

-10

0

10

20

30

40

50

60

70

3+00.00

1395

1395

1390

1390

1385

1385

-70

-60

-50

-40

-30

-20

-10

0

10

20

30

40

50

60

70

