


AFTW-50  
2200B, 551-600

SPECIAL CIRCUITS N  
6203 FORWARDED N  
PERMIT REQUIRED N



OPERATING RANGE OF JOB STEPS  
LINE 1 TO 6  
SPLICE 51 TO 51  
MFRC 45C

TRANSMISSION ZONE  
RZ 15 CZ 0 TAPER CODE 1237

CAUTION HIGH VOLTAGE  
KV 7.20 AERIAL N BURIED N

POLE CONTACTS (+) 0 (-) 0  
PWR CO K.G. & E,

NOTES

ORDER NO. 4866743

TOT.PRINTS 13 PRINT NO. 10  
NPA/NNX: 316-681 PRT: 316681  
EXCH. WICHITA MURRAY  
TAX DIST. SG501  
GEO LOC. KL8001  
ENGR. RA DRAWN AGS  
TELEPHONE NO. (316) 268-2601  
REC. REF. A-46A\*  
MAP REF.  
SCALE NONE  
ISSUE DATE  
DATE REV.  
JOB TITLE 21ST-HILLSD TO OLV

11  
PRINT  
SEE

9  
PRINT  
SEE