

IRONS

Point Table			
Point #	Northing	Easting	Raw Description
100	6460.47	8741.48	iron
101	6524.47	8741.00	iron
102	6525.01	8813.00	iron
103	6461.01	8813.48	iron
104	6593.52	8880.48	iron
105	6594.00	8944.48	iron
106	6436.03	8894.36	iron
107	6470.91	8940.69	iron
108	6422.68	9037.37	iron
109	6364.68	9037.37	iron
110	6364.68	9063.48	iron
111	6422.68	9063.48	iron
112	6472.68	8866.76	iron
113	6507.57	8913.10	iron
114	6514.46	9180.89	iron
115	6500.45	9237.18	iron
116	6689.47	9284.22	iron
117	6703.48	9227.94	iron
118	6412.50	8915.58	iron
119	6374.19	8965.76	iron
120	6394.42	8903.59	iron
121	6362.37	8951.93	iron
122	6333.80	8943.43	iron
123	6333.37	8885.43	iron
124	6277.36	8885.85	iron
125	6277.79	8943.85	iron

SWS

Point Table			
Point #	Northing	Easting	Raw Description
7000	6802.29	9106.62	0+00
7001	6780.29	9078.13	0+36.0
7002	6611.30	9079.39	2+05.0
7003	6482.55	9080.32	3+33.7
7004	6417.47	9102.38	4+02.5
7005	6383.68	9112.83	4+37.8

