






EASEMENTS MUST BE RESTORED TO THE CORRECT ELEVATION AFTER STORM SEWER CONSTRUCTION. COST SUBSIDIARY TO BID ITEM FOR EASEMENT GRADING.

-  Curlex Blanket (3108 Square Yards)
-  ① Inlet Sediment Barrier (6 each)
-  ② Outlet Sediment Protection (2 each)

Contractor to ensure easements are graded to the correct elevations and that the easements are graded uniformly. Cost for easement maintenance is subsidiary to bid item for Easement Grading.



SCALE 1" = 20'

Fawn Grove at Sunset Lakes Phase 3 Easement Grading & Erosion Control Plan WICHITA, KANSAS		DESIGN E.J.G DRAWN E.J.G REVIEW UTILITY	SHEET 8 OF 24
 Ruggles & Bohm, P.A. Engineering, Surveying, Land Planning 924 North Main Wichita, Kansas 67203 www.rbkansas.com		(316) 264-8008 (316) 264-4621 fax E-mail: info@rbkansas.com	PROJECT NUMBER 472-81408 DATE April 27, 2008
DRAWING FILE SWS [Erosion Map]		DATE April 27, 2008	