


BENCHMARKS

BM #1: Brass Plate on North
Hub Guard of R.C.B.C. 50' East of
NW Corner NE 1/2, Sec. 22, Twp.
26-S, R-1-E.
Elev. = 1371.83 (NGVD29)


BM #2: "X" cut on East Hub
Guard of R.C.B.C., 110' S. of the
SE Cor., SE 1/4, Sec. 22, Twp.
26-S, R-1-E.
Elev. = 1359.54 (NGVD29)



SEWER SERVICE TABLE

NUMBER	TYPE	LOCATION			STATION\ DIRECTION	FOR INFORMATION ONLY	
		LOT NO.	BLOCK NO.	LINE NO.		APPROXIMATE LENGTH 4" PIPE	
43	10" x 4" Tee Saddle	17	E	5	0+40/Rt.	4.0'	13'
44	10" x 4" Tee Saddle	18	E	5	1+74/Rt.	4.5'	13'
45	10" x 4" Tee Saddle	19	E	5	2+68/Rt.	5.0'	13'
46	10" x 4" Tee Saddle	20	E	5	3+34/Rt.	5.0'	13'

NOTE: Vertical Riser Pipe shall be extended to 2' minimum above ground water elevation and 4' maximum below proposed ground elevation.



Falcon Falls 2nd Addition
LINE 5
SANITARY SEWER IMPROVEMENTS

PROJECT NUMBER
468-84065

DESIGN
TJW

APPROVED
AEG

SCALE
Noted
SHEET
15 OF 32

REVISIONS

DATE
10/05/05

F:\eng\Falcon Falls 2nd\SS\ss014.dwg

0508E344