



- 2002-02486 91102 - 2609 E Stadium - Wichita Exc - 2 twin CO, 2122, 2122, 38' NE of MH 0100 (0+38)
4" city Predco Saddle
- 2002-01360 - 5/15/02 - 2620 E Shady brook - AE Henning - 123' w of MH 2+61.2 (+41.2) 1V45 Predco Saddle
4" SCH 40 PVC, Replaced last 10' on low end
- 2003-02196 - 8/21/03 - 2710 E Shady brook Ln - Jones SWR - Replace entire line - 4" PVC 2V45, 1V22,
2H22, city main repair - existing 4" SE from DEMH 3+44.3 - Replaced clay with plastic, 4" PVC stub

| CONSTRUCTION RECORD | | | | | SERVICE RECORD | | | | | | | |
|---------------------|-----------|--------|-------|-------------|---------------------|------------|---------------|-------------------|--------------|---------------|------------------|--|
| STATION | ELEVATION | | Depth | MANHOLE | 4-INCH "Y" BRANCHES | | No. of Permit | | House Number | | DATE OF PERMITS | |
| | Ground | Grade | | | North | South | North West | South East | North West | South East | North West | South East |
| 0+0 | 131.30 | 124.00 | 7.3 | 0+0 | 0+44.0 | 0+47.0 (R) | #820 | 200250614 | 2402-5 | 2402-4 | 7-7-43 | carried back to clay - 1' from main 3-7-02 6-14-43 |
| 1+0 | 132.00 | 124.89 | 7.1 | | 0+86.0 | 0+89.0 | #821 | | 2434-11 | 2408-10 | 7-7-43 | |
| | | | | | 1+13.6 | 1+22.5 (R) | #710 | | Stadium Dr. | E. 20th | | 6-14-43 |
| | | | | | 1+56.0 | 1+59.0 | #822 | | 2415-17 | 2414-16 | 7-7-43 | |
| 2+0 | 133.70 | 125.78 | 7.9 | | 1+85.8 | 2+04.0 (R) | #711 | 21655 | Stadium Dr. | E. 20th | 7-7-43 | 10-12-88 6-14-43 |
| | | | | | 2+34.2 | 2+37.2 | #823 | | 2421-23 | 2420-22 | 7-7-43 | |
| | | | | | 2+59.3 | 2+76.7 (R) | #712 | | Stadium Dr. | E. 20th | | 6-14-43 |
| 3+0 | 136.70 | 126.67 | 10.0 | 3+10.3 | 3+31.3 | 3+53.5 (R) | #713 | 065144 824 | 2503-5 | 2502-4 | 2-27-78 7-7-43 | 6-14-43 |
| | | | | | 3+80.0 | 3+83.0 | #825 | | 2509-11 | 2508-10 | 7-7-43 | |
| 4+0 | 140.40 | 127.57 | 12.8 | | 4+05.2 | 4+28.6 (R) | #714 | | Stadium | E. 20th | 7-7-43 | 6-14-43 |
| | | | | | 4+25.6 | 4+74.4 | #826 | 22989 | 2515-17 | 2514-16 | 4-21-89 7-7-43 | |
| 5+0 | 141.30 | 128.46 | 12.8 | | 5+08.0 | 5+11.0 | #715 | | Stadium | E. 20th | 7-7-43 | 6-14-43 |
| | | | | | 5+49.5 | 5+52.5 | #827 | 43234 | 2521-23 | 2520-22 | 3-15-85 7-7-43 | |
| | | | | | 5+81.0 | 5+84.0 | #828 | 061330 | 2521-23 | S. 6. 2520-22 | 7-7-43 | 5-27-77 6-14-43 |
| 6+0 | 141.30 | 129.35 | 11.95 | | 6+08.1 | 6+11.1 (R) | #716 | | Stadium | E. 20th | 7-7-43 | |
| | 141.50 | 129.54 | 11.96 | 6+17.7 | 6+76.0 | 6+79.0 | #829 | | 2603-5 | 2602-4 | 7-7-43 | |
| 7+0 | 140.60 | 130.26 | 10.34 | | 7+01.0 | 7+04.0 | #830 | | Stadium | E. 20th | 7-7-43 | |
| | | | | | 7+24.9 | 7+27.9 (R) | #1514 | | 2609-11 | 2608-10 | 7-7-43 | 11-18-91 6-14-43 |
| | 141.10 | 131.00 | 10.10 | 7+78.2 | 7+41.2 | 7+44.2 | #831 | 2007560 | 2621-23 | 2618-20 | 7-7-43 | see next pg 2-16-66 |
| | | | | | 7+94.2 | 7+97.2 | #718 | | Stadium | E. 20th | 7-7-43 | |
| 8+0 | 140.70 | 131.03 | 9.67 | | 8+33.0 | 8+36.0 (R) | #718 | | 2532-34 | 2531-33 | | 6-14-43 |
| | | | | | 8+79.1 | 8+88.0 (R) | #719 | | 2533-40 | E. 20th | | 6-14-43 |
| 9+0 | 140.80 | 131.23 | 9.57 | | | | | | | | | |
| | 140.90 | 131.24 | 9.66 | 9+06.0 | | | | | | | | |
| 0+0 | 141.10 | 131.50 | 9.60 | 0+0 | 0+31.5 | 0+34.5 | #720 | | 2615-17 | 2614-14 | | 6-14-43 |
| | | | | | 0+58.4 | 0+61.4 (R) | #831 | | Stadium | | 7-7-43 | |
| 1+0 | 142.30 | 132.24 | 10.06 | | 0+88.0 | 0+91.0 | #832 | | 2621-23 | 2618-20 | 7-7-43 | see next pg 5-15-02 6-14-43 |
| | | | | | 1+16.0 | 1+19.0 | #832 | | Stadium | Shadybrook | 7-7-43 | |
| | | | | | 1+37.4 | 1+40.4 (R) | #832 | | 2621-23 | 2620-26 | | 6-14-43 |
| 2+0 | 143.20 | 132.97 | 10.23 | | 1+70.4 | 1+73.4 | #722 | | 2624-26 | Shadybrook | | 6-14-43 |
| | 143.70 | 133.41 | 10.29 | 2+64.2 | 2+07.8 | 2+13.6 (R) | #722 | | | | | |
| | | | | | 2+43.7 | 2+50.7 | #722 | | | | | |
| 3+0 | 144.10 | 133.70 | 10.40 | 4" sub S.E. | 2+74.4 | 2+77.4 | #832 | 026180 34-08169-7 | 2623-25 | 2622-24 | 1-19-90 7-7-43 | 11-14-91 6-14-43 |
| | 144.30 | 134.00 | 10.30 | 3+44.3 | 3+05.3 | 3+08.3 | #832 | 2003 02196 | Stadium Blvd | Shadybrook | 7-7-43 | 8-21-03 6-14-43 |
| 0+0 | 131.90 | 122.34 | 9.56 | 0+00 | 0+45.3 (R) | 0+48.3 (R) | #903 | 5247 | 2402-5 | 2402-4 | 7-26-43 | 2-05-82 7-26-43 |
| | | | | | 0+83.9 | 0+86.9 | #904 | | E. 20th | Shadybrook | 7-26-43 | |
| 1+0 | 133.50 | 123.26 | 10.24 | | 1+26.5 (R) | 1+23.5 (R) | #904 | #917 | 2409-11 | 2408-10 | 7-26-43 | 7-26-43 |
| | | | | | 1+63.8 | 1+62.8 | #905 | 916 | E. 20th | Shadybrook | 7-26-43 | 7-26-43 |
| 2+0 | 134.80 | 124.18 | 10.62 | | 2+06.8 (R) | 2+03.8 (R) | #905 | 916 | 2415-19 | 2414-16 | 7-26-43 | 7-26-43 |
| | | | | | 2+57.2 | 2+39.3 | #907 | 19481 | 2421-23 | 2420-22 | 7-26-43 | 11-0-87 7-26-43 |
| 3+0 | 135.70 | 125.10 | 10.60 | 3+07.4 | 2+85.3 (R) | 2+82.3 (R) | #907 | 915 | E. 20th | Shadybrook | 7-26-43 | 7-26-43 |
| | | 125.18 | | | 3+34.5 | 3+15.8 (R) | #906 | 914 | 2503-5 | 2502-4 | 7-26-43 | 7-26-43 |
| | | | | | 3+71.5 (R) | 3+58.9 (R) | #906 | 914 | E. 20th | Shadybrook | 7-26-43 | 7-26-43 |
| | | | | | 3+92.4 | | #907 | 915 | 2509-11 | 2508-10 | 11-09-88 7-26-43 | 7-26-43 |
| 4+0 | 136.80 | 126.02 | 10.78 | | 4+20.0 | 4+35.8 (R) | #907 | 915 | E. 20th | Shadybrook | 7-26-43 | 7-26-43 |
| | | | | | 4+51.0 (R) | 4+35.8 (R) | #908 | 912 | 2515-17 | 2514-16 | 11-14-91 7-26-43 | 7-26-43 |
| | | | | | 4+92.7 | 4+74.3 | #908 | 912 | E. 20th | Shadybrook | 7-26-43 | 7-26-43 |
| 5+0 | 138.10 | 126.94 | 11.16 | | 5+14.0 (R) | 5+11.0 (R) | #908 | 912 | 2521-23 | 2520-22 | 7-26-43 | 7-26-43 |
| | | | | | 5+47.4 | 5+44.4 | #909 | 917 | E. 20th | Shadybrook | 7-26-43 | 7-26-43 |
| | | | | | 5+72.0 (R) | 5+84.3 (R) | #909 | 917 | 2521-23 | 2520-22 | 7-26-43 | 7-26-43 |
| 6+0 | 139.00 | 127.86 | 11.14 | | 6+00.0 (R) | | #910 | | 2526-28 | Shadybrook | 7-26-43 | 7-26-43 |
| | 139.30 | 128.00 | 11.30 | 6+14.1 | 4" sub S.E. | 4" sub E. | #910 | | | | 7-26-43 | |

#1834 - Repair - 2520-22 Stadium Dr. - Joe Mac Donald - 8-25-51