



LAT. 10, SUBMAIN 3, W.I.S.
 W. B. CARTER
 BK. JF. 64, PROJ. NO. C22-75
 JAN. 22, 1953

CONSTRUCTION RECORD

SERVICE RECORD

Line # 1

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
0+0	125.9	118.00	7.9	0+00 New MH.								
1+0	127.3	118.40	8.9									
2+0	128.5	118.80	9.7									
	128.6	118.84	9.8	2+08.7								
3+0	129.8	119.20	10.6									
4+0	130.2	119.60	10.6									
	132.1	122.01 in	10.1	4+94.6								
5+0					5+23.3	5+20.3	#5713	#6764	1750 R Windsor	1749 R Woodlawn	1-24-80	1-24-80
					+73.0	+70.0	#5712	#6765	1744 Windsor	1743 Woodlawn	7-3-53	10-24-53
6+0	134.4	122.40	12.0		6+35.0	6+32.0	#5711	#238	1738 Windsor	1737 Woodlawn	7-3-53	3-2-54
					+86.3	+83.3	#5710	#239	1732 Windsor	1731 Woodlawn	7-3-53	3-2-54
7+0	134.9	122.80	12.1		7+39.0	7+36.0	#5709	#240	1726 Windsor	1725 Woodlawn	7-3-53	3-2-54
					+91.9	+88.9	#5708	#251	1720 Windsor	1719 Woodlawn	7-3-53	12-18-53
8+0	136.8	123.20	13.6									
	136.7	123.25	13.4	8+20.9	8+40.4	8+37.4	#5707	#250	1714 Windsor	1713 Woodlawn	7-20-72	12-18-53
					+93.4	+90.4	#5706	#403	1708 Windsor	1707 Woodlawn	7-3-53	9-10-53
9+0	135.7	123.60	12.1		9+48.5	9+45.5	#5705	#402	1702 Windsor	1701 Woodlawn	7-3-53	9-10-53
10+0	134.9	124.00	10.9		10+68.5	10+65.5	#5704	#401	1696 Windsor	1695 Woodlawn	7-3-53	9-10-53
11+0	135.7	124.40	11.3		11+29.1	11+26.1	#5703	#400	1690 Windsor	1689 Woodlawn	7-3-53	9-10-53
	136.0	124.53	11.5	11+39.6	11+81.8	11+78.8	#5157	#6399	1652 Windsor	1651 Woodlawn	5-9-53	9-10-53
12+0	136.1	124.80	11.3		12+33.7	12+30.7	#5156	#6398	1646 Windsor	1645 Woodlawn	5-9-53	9-10-53
					+85.9	+82.9	#5155	#6397	1640 Windsor	1639 Woodlawn	5-9-53	9-10-53
13+0	135.8	125.20	10.6		13+34.7	13+31.7	#5154	#6396	1634 Windsor	1633 Woodlawn	5-9-53	9-21-89
					+90.8	+87.8	#5153	#6395	1628 Windsor	1627 Woodlawn	5-9-53	9-10-53
14+0	134.5	125.60	8.9		14+41.4	14+38.4	#5152	#6394	1622 Windsor	1621 Woodlawn	5-9-53	9-10-53
	134.3	125.80	8.5	14+58.0								



City Directory shows these addresses on Fabrique 1730, 1736, 1740, 1746, 1750, 1756, 1762 these addresses do not go along with what is in sewer map

Line # 2

0+0	130.6	119.00	11.6	0+00 = 2+08.7 in Line # 1	4+40 PVC- 0+29.8	4+40 PVC- CO 0+26.8	#4991	#2033	1762 R Windsor	1761 R Windsor	1-14-03 see below	3-3-54
					+78.5	0+75.5	#4990	#2032	1756 R Windsor	1755 R Windsor	4-28-53	4-28-53
1+0	132.6	119.40	13.2		1+32.9	1+29.9	#4989	#2031	1750 R Windsor	1749 R Windsor	4-28-53	3-3-54
					+81.4	+78.4	#4988	#2030	1744 R Windsor	1743 R Windsor	4-28-53	3-3-54
2+0	132.8	119.80	13.0		2+34.8	2+31.8	#4987	#2029	1738 R Windsor	1737 R Windsor	4-28-53	10-14-53
					+88.0	+85.0	#4986	#2028	1732 R Windsor	1731 R Windsor	4-28-53	10-14-53
3+0	130.5	120.20	10.3		3+39.2	3+36.2	#4985	#2027	1726 R Windsor	1725 R Windsor	4-28-53	10-14-53
	130.1	120.29	9.8	3+21.7	+95.2	+92.2	#4984	#2026	1720 R Windsor	1719 R Windsor	4-28-53	10-14-53
4+0	129.8	120.60	9.2		4+43.3	4+40.3	#4983	#2025	1714 R Windsor	1713 R Windsor	4-28-53	10-14-53
5+0	128.6	121.00	7.6		5+66.1	5+63.1	#4982	#2024	1708 R Windsor	1707 R Windsor	4-28-53	3-2-53
6+0	130.4	121.40	9.0		6+22.0	6+17.0	#4981	#2023	1702 R Windsor	1701 R Windsor	4-28-53	3-2-53
	130.9	121.57	9.3	6+43.5	+78.0	+75.0	#4980	#2022	1696 R Windsor	1695 R Windsor	4-28-53	3-2-53
7+0	132.1	121.80	10.3		7+30.0	7+27.0	#4979	#2021	1690 R Windsor	1689 R Windsor	4-28-53	3-2-53
					+78.6	+75.6	#4978	#2020	1684 R Windsor	1683 R Windsor	4-28-53	3-2-53
8+0	133.6	122.20	11.4		8+30.0	8+27.0	#4977	#2019	1678 R Windsor	1677 R Windsor	4-28-53	3-2-53
					+84.7	+81.7	#4976	#2018	1672 R Windsor	1671 R Windsor	4-28-53	3-2-53
9+0	133.5	122.60	10.9		9+56.2	9+53.2	#4975	#2017	1666 R Windsor	1665 R Windsor	4-28-53	3-2-53
	133.8	122.86	10.9	9+65.6			#4974	#2016	1660 R Windsor	1659 R Windsor	4-28-53	3-2-53

2003-00129-114163-1762 S Fabrique - Mies Const - Lower part - 1722, 1745 - City Wye repair - 4" Predco 29' N of MH 0+00(0+29)

2001-00365-21201-1628 S Fabrique Dr - Padgett Ex - 4" SCH 40 Donut 29.7'S of MH 9+65.6(9+35.9) ITWIN CO, 2V22, 1H22, 1 Fernco to CI @ house - msmt good

2002-02487-910102-1713 S Woodlawn - Wichita Exc - 4" PVC, ITWIN CO, 1V45, 1H22, City Wye repair 4" Predco 16.6' N of MH 8+20.9(8+37.5) Shallow

2002-03391-1211602-1628 S Windsor - Reddi Rootr - Pipeburst replacement 4" PESDR17 - 4" PVC ITWIN CO, 1V45 - City Wye repair - 4" Predco 17'S of MH 14+58(14+41)

91-01474 12-15-94 1762 S Fabrique Dr

(2129.7) 071498-1746 S Fabrique - Repair - 4-30-79

see above #5153 - tap - 1628 Windsor - 5-9-53 - Nichell Hensley, Inc. #91-26157-7 7/9/91-1737 S. Woodlawn - NIC-

2001-00673-#5702 - tap - 1658 Windsor - 7-3-53 - Nichell + Hensley, Inc. - 3/28/01 - AE Henning - 4" SCH 40 Donut 36.6' N of MH + 3' from main (11+76.2)

#6396 - tap - 1639 S Woodlawn - 9-10-53 - Nichell + Hensley, Inc.

#4324 - tap - 1646 Fabrique - 3-2-53 - Eugene Rupprecht

#14955 - tap - 1643 S Woodlawn - 10-2-61 - Headgate Reg. (11+45.6)

#21801 - New Conn. 10-28-88 - 1664 S Windsor - (11+17.6 TAP) - 4" ABS 40

10-28-90 1664 S Windsor 5/0 - 11+29.0 -