

CONSTRUCTION RECORD

SERVICE RECORD

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS		
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East	
Line #1 0+0	93.6	88.90	4.7	0+00 New MH	0+78.0	0+75.0		#6497	2320 S. Wichita			9-16-55	
1+0	93.4	89.0	4.4		1+30.0 1+84.5	1+27.0 1+81.5		#10498 2001-23113 #1317	216 Patterson 210 W R Patterson			9-16-55 12-7-56 7-2-56	
2+0	93.0	89.10	3.9		2+46.5 2+94.0	2+43.5 2+91.0		#717	204 Patterson			5-8-56	
3+0	93.0	89.20	3.8	2+99.3	3+49.5	3+46.5		#4764	122 R Patterson			5-12-55	
4+0	93.0	89.35	3.7		4+14.0 4+72.0	4+11.0 4+69.0		204 #4763 #4762	116 Red Patterson 115 Patterson			4-5-54 5-12-55 5-12-55	
	93.3	89.38	3.9	4+79.4									
Line #2 0+0	96.1	89.20	6.9	0+00 New MH.	0+77.0	0+74.0							
1+0	97.5	89.30	8.2		1+41.0 1+80.5	1+38.0 1+83.5	3104 3754	20908 C37613 209 Patterson	215 Patterson 244 W R 33rd St			6-21-56 3-14-73 2-14-57	
2+0	95.9	89.40	6.5		2+29.0 2+84.0	2+32.0 2+87.0	2155 3103	18-24357 209 R Patterson				12-16-48 2-14-57 11-20-56	
3+0	95.9	89.50	6.4	3+00.0	3+48.5	3+51.5	#4766	121 Patterson				5-12-55	
4+0	94.4	89.60	4.8		4+01.0 4+70.0	4+04.0 4+73.0	#4765	C3613 Patterson	115 Patterson 232 W 33rd St (see below)			5-12-55 6-20-67	
	94.0	89.68	4.3	4+79.5									
	104.2	99.68	4.5	0+00 Existg MH	WEST 0+32.1 0+42.0 0+74.6	EAST 0+29.1 0+48.0 0+71.6							
1+0	104.0	99.78	4.2		1+13.0 1+74.8	1+10.0 1+71.8	21627 6896	1412 (move) S. Hiram 1908 S. Hiram	1915-2510 Enclid (see below)			7-6-84 4-30-63	
2+0	104.2	99.88	4.3		2+20.0 2+71.8	2+17.0 2+44.0	C20929 C20930	1919 Enclid 1921 S. Hiram				1-8-80 9-10-71 3-10-59 9-10-70	
3+0	104.2	99.98	4.2	3+00.0	3+17.0 3+59.4	3+14.0 3+56.4	C20931 C33262	6135 C37671	1932-34 S. Hiram 1938 S. Hiram	1929 Enclid 1-2-3 1935 Enclid			9-10-70 7-9-82 6/29/72 13-13-73
4+0	103.6	100.08	3.5		4+20.4 4+69.7	4+17.4 4+54.5 4+97.0	C11693 C17180	6674 5762	1942 S. Hiram 1946-52 Hiram 1945 Enclid			11-26-68 10-13-55 12-3-69 11-26-57	
5+0	103.2	100.18	3.0		5+27.2 5+52.6 5+61.0	5+42.7 5+47.5 5+76.2	C21600 #21604 C27554 1799	#1167 B5766 1924 may	1954-605 Hiram 1958 Hiram 2 May			11-2-70 6-19-56 10-4-56 17-4-66 11-7-80	
	103.2	100.28	2.9	5+80.6									

Line #1

Line #2

LAT. 6, DIST. E, S. S. # 21

Nic 1924 May 11-7-80 (214.5+80.6) Service

Top Sec 15 6135 - Spec Fee 100⁰⁰ (Latinal) 02 3-14-73 - 244 W. 33rd St (1+38)

Top C20928 - 1916-18 S. Hiram - Gerald Thompson 9-10-70 (1+39.4)

Sub 33rd St - B 6140 - 1915 Enclid - Turnbull - 8-8-66 top (1+31)

#1300 - Top - 1280 Patterson - 7-2-56 - Frederick Bell Co.

#0665 - Top - S. Hiram - 1962 S. Hiram - December - 10-4-56

3756 - 6th St - 3330 S. Wichita - 2-14-57

#4182 - Top - 1935 S. Enclid - December - 4-18-62 C23813 - Seal off - al Henning - 4-19-71

#16345 - Top - 1901 Enclid - Yenn Lippold - 11-13-62 (73' E. of M.N. 0+0) See G48 for repair info

#3042 - Seal off - 1950 S. Hiram - Richard Thompson - 4-5-65

#23038 - Special Fee #25⁰⁰ - Pl. 6/20/67 - Linger Rly - 232 W. 33rd St. So.