

2001-00756-4-4-01- 3329 S Hiram - Redd Rootr - 4" SCH40 4" Wye Repair 39' sd of MH 9+10 (9+49) Replaced entire line - ATWIN CO,
1H22, 6H22, 2KICKOUTS, 1H45

note - work done by homeowner without permit & inspection
5/6 3355 S. Hiram - 11/2/00 - Wichita Exc - 4" TAP INTO MH done by homeowner slo on s-se side of MH
Rep 3355 S. Hiram - 11/2/00 - Wichita Exc - 4" SCH40 - Replace all but lower 2' of sewer - ATWIN CO, 1H22, 1H45