



2001-00449-3/1/01-Kansas Ditch-4"SCH40-Replaced all but lower 1'-ITWIN CO, 1V22,

LAT. 9, SUB. 3, S. S. 22

BUILDERS CONST. INC.,

MAY 31, 1955

BK. NO. K-28.

PROJ. NO. C25-17

CONSTRUCTION RECORD

SERVICE RECORD

Line #3

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS		
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East	
													East
0+0	101.7	94.30	7.4	1109.3 Line 2 0+00	East	West							
					0+24	0+27		5177	2118 S Everett			8-21-57	
					0+78	0+81		5176	2118 S Everett			8-21-57	
1+0	101.8	94.50	7.3										
					1+33.5	1+36.5		5125	2216 S Everett			8-21-57	
					1+97				2209 Bennett		11-21-80		
2+0	102.1	94.70	7.4			2+00							
	102.1	94.80	7.3	2+51									
					2+64	2+67		5585	2204 S Everett			11-6-57	
3+0	102.1	94.90	7.2										
					3+09.7	3+12.7		6143	2161 S Bennett	2162 S Everett	1-16-58	11-6-57	
					3+75.5	3+78.5		6144	2156 S Bennett	2157 S Everett	1-16-58	11-6-57	
4+0	102.3	95.10	7.2										
					4+36.5	4+39.5		6145	2149 S Bennett	2150 S Everett	1-16-58	11-6-57	
					4+88.5	4+91.5		16059	2143 S Bennett	2144 S Everett	8-21-62	11-6-57	
5+0	102.3	95.30	7.2										
				5+02									
					5+50	5+53		10260	2151 S Bennett	2152 S Everett	5-11-59	11-6-57	
6+0	102.3	95.50	6.8										
					6+10	6+13		7418	2131 S Bennett	2132 S Everett	7-18-58	3-15-68	
					6+62	6+65.9		69109	2127 S Bennett	2126 S Everett	7-14-58	10-27-78	
	102.3	95.66	6.6	6+80.8									
Line #3A	0+0	101.7	94.14	7.6	1109.2 Line 2 0+0								
						0+24.3	0+27.3	5710	2231 S Bennett	2131 S Everett	11-15-57	8-21-57	
						+78.4	0+81.4	5709	2231 S Bennett	2131 S Everett	11-15-57	8-21-57	
	101.7	94.50	7.2	0+90.6									
Line #4	0+0		94.60		0+00 Existg MH	North	South						
						0+36.0	0+39.0	6788	3308	2127 Jewell	2130 Kila	10-25-55	12-11-56
						0+92.5	0+95.5	6787		2121 Jewell		10-25-55	
1+0	102.4	94.80	7.6										
						1+56.0	1+59.0	6786		2115 Jewell		10-25-55	
2+0	102.2	95.00	7.2										
						2+22.0	2+25.0	6783		2109 Jewell		1-22-55	
						2+83.0	2+86.0	6782	2699	2103 Jewell	2040 Kila	10-25-55	10-8-56
3+0	101.8	95.20	6.6	3+00.0									
						3+50.5	3+53.5	6551	2395	2033 Jewell	2034 Kila	9-21-55	9-18-59
4+0	101.5	95.40	6.1										
						4+71.5	4+74.5	6549	2395	2027 Jewell	2028 Kila	9-21-55	9-25-59
						4+69.0	4+72.0	6549	2396	2027 Jewell	2028 Kila	9-21-55	10-26-56
5+0	101.4	95.60	5.8										
						5+33.0	5+36.0	6549	2396	2005 Jewell	2010 Kila	9-21-55	10-26-56
6+0	101.6	95.80	5.8	6+01.0									
						6+48.7	6+51.7	6549	2396	2003 Jewell	2004 Kila	1-21-57	10-26-56
7+0	101.6	96.00	5.6										
						7+74.0	7+77.0	6543	4724	1922 Jewell	1732 Kila	7-11-55	1-19-56
8+0	102.1	96.20	5.9										
						8+37.0	8+40.0	6542	4724	1926 Jewell	1926 Kila	7-11-55	1-19-56
9+0	102.6	96.40	6.2										
	102.6	96.40	6.2	9+01.7									
						9+59.0	9+62.0	6541	4724	1927 Jewell	1926 Kila	7-11-55	10-4-56
10+0	102.4	96.60	5.8										
						10+17.0	10+20.0	6538	4763	1927 Jewell	1927 Kila	7-11-55	10-27-56
11+0	102.4	96.80	5.6										
						11+39.0	11+42.0	6537	4763	1927 Jewell	1927 Kila	7-11-55	7-3-57
						11+92.0		6536	4763	1927 Jewell	1927 Kila	7-11-55	3-31-00

Line #4 Continues on page 65.

58 Rose #5574 - top - 2003 Jewell - Home Pkg. Co. - 7-11-55 #5712 - top - 2201 Bennett - 11-15-57
 #6124 - top - 2102 Kila - Home Pkg. Co. - 8-23-55 (4453) #5715 - top - 2205 Bennett - 11-15-57
 #6135 - top - 2108 Kila - Home Pkg. Co. - 8-23-55 (6700) #6170
 3309 top 2114 Kila Home Pkg. Co. 10-11-56 (R) (0+99.9) #25341 - 51810 - 2227 S Bennett - Kapaik - 4" sDR35
 5549 Top 2105 S Bennett 11-5-57 Home Pkg. 4" wye 6' N of MH. Repl. all but lower 2' of line.

3/31/00-2000-00762-1921 W Jewell Ave - R - Lubbers - 4" SCH 40 - 4" Wye repair - 9' w of MH 12+01.12 (MH 921.2)
INST - IRWIN CO, 1V22, 1H22