



2001-01916-81201-6220 E 10th - AE Henning - 4" sch 40 - Fernco to clay 2' from main,
 Fernco to EI @ house, ITW in CO

13680 tax 6207 E 10th Reginald 12-28-60 (4+50)
 #B-17. Tax - 1135 Patricia - Phil's Plumbing Service (4+46)

RECONNECTIONS

STA.	ADDRESS	DIRECTION
13+12.1	6220 N. 10TH ^R See above	SOUTH
12+98	6213 N. 11TH	NORTH
12+04.7	6302 N. 10TH	SOUTH
12+02.7	6301 N. 11TH	NORTH
11+32.5	6308 N. 10TH	SOUTH
11+30.1	6305 N. 11TH	NORTH
10+59.6	6314 N. 10TH	SOUTH
10+57.8	6309 N. 11TH	NORTH

SANITARY SEWER RESPONSE PLAN
 PHASE IA
 PROJ. NO. 468-82420 (623124)
 BUILT BY INSITUFORM PLAINS, INC.
 BOOKED 2-29-96 FROM AS BUILTS

LAT. 42, D.C.S. # 2, S.S. # 12
 W. B. CARTER CONST. CO. INC. FEB. 9, 1956
 BK. NO. K-27, PROJ. NO. C.25-78

CONSTRUCTION RECORD

SERVICE RECORD

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS		
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East	
Line #1 0+0	200.1	192.00	8.1	0+00 Exist'g MH									
1+0	199.4	192.30	7.1										
2+0	199.2	192.50	6.7										
3+0	199.3	192.70	6.6										
4+0	198.9	192.90	6.0										
5+0	197.5	193.10	4.4										
6+0	198.0	193.30	4.7										
7+0	198.1	193.51	4.6	7+06.8									
8+0	198.9	193.70	5.2										
9+0	198.5	193.90	4.6										
10+0	198.9	194.10	4.8										
11+0	199.9	194.40	5.5	10+19.3	8" stub N.	10+52.5	10+54.5	4391	4869	6209 E. 11th	6314 S. 10th	5-2-57	7-9-57
12+0	200.8	194.60	6.2					9549	7744	6305 E. 11th	6305 E. 11th	3-4-59	4-26-53
13+0	202.2	194.80	7.4					12731	815	6201 E. 11th	6209 E. 11th	5-3-60	4-4-56
14+0	203.9	196.32	7.6	13+19.1									
15+0	205.3	196.72	8.6					7370	15922	6205 E. 11th	6208 E. 10th	6-26-57	3-25-56
16+0	207.0	197.15	9.9	16+06.0				5181	953757	6201 E. 11th	6208 E. 10th	9-3-57	3-8-55
Line #2 0+0	199.5	192.98	6.5	0+00 = 3+87.0 in Line #1				963372	4207				3-29-56
1+0	200.3	193.38	6.9		4" PVC 40	0+37.5	0+39.5						9-20-56
2+0	201.6	193.78	7.8					4423	1184	6316 Beachy	6316 Beachy	7-26-57	3-10-56
3+0	203.1	194.18	8.9	3+00.0				#744		6302 Beachy			6-21-57
4+0	204.0	195.40	8.6					3081	1148 R Patricia			2-26-57	11-19-56
5+0	205.4	195.80	9.6					7671	590	6229 R Patricia	6229 R Patricia	12-12-56	3-23-51
	206.2	196.19	10.0	5+98.0 (4" stub N.)				6979	4268	6200 Beachy	6212 Beachy	6-7-58	4-5-57
Line #3 0+0	198.5	193.62	4.9	0+00 = 7+06.8 in Line #1				#287					3-21-56
1+0	199.6	194.02	5.4					#752					2-8-56
2+0	201.0	194.42	6.6										
3+0	202.3	194.82	7.5	3+00.0				4213	6213	6213		9-24-56	
4+0	203.8	196.40	7.4					4288	4288	6213 Patricia			5-3-57
5+0	205.4	196.80	8.6					2870	6213	1143 Patricia		6-25-57	3-18-51
	205.9	196.96	8.9	5+39.0				2435	2570	6205 E. 11th	1127 R Patricia	3-15-57	9-25-56

2001-00650-3/23/01-6232 E Beachy - Reddi - 4" SCH 40 - Replace 6' upper end - ITW/INCO

#5732 Top 6202 E. 11th St. 2+8. jly ca. 2-29-56
 #901 Top 6202 Beachy 10-26-56 Arlan Ray
 #2992 - Top 6203 E. 11th - Leo Griffin - 11-8-56
 96-12757 3962 - Top 12th Patricia - 5-1-57
 no. 2773 - \$50.00 special fee paid 6213 E. 11th Wm. T. Mann Co. 4-25-58
 #6994 Top \$50.00 special fee paid 6209 E. 11th C. D. Owens 5-22-58 alternating Policy
 (\$50.00 special fee paid for 6205 E. 11th Owens 5-25-58) see 66140
 (\$50.00 spec. fee paid 5-4-59 see 18087) 6305 E. 11th Reynolds 3-4-59
 4604 - 30 - 6222 Beachy - small - 5-8-57
 #4372 - 6313 E. 10th Building - 6-17-57
 #4926 - 1226 - 1143 Patricia - 5-7-57
 62332 Top 6213 E. 11th Patricia - 5-7-57
 #12731 - Spec. Fee - 6301 E. 11th - Bradford Service 5-3-60 - \$50.00
 line separated, repaired w/4" Fernco 1-7-59
 10-14-56