



CK with Calvin
 Re status of Lines
 Crossing
 V. Huns said
 to get with
 Watcher Sewer
 or Best Way to
 serve these
 lots
 to
 AVE.

Block E
 PLAY AREA #2
 unable to locate

Locations and measurements
 as found by Sewer Maint.
 Nov. 1982

CONSTRUCTION RECORD

SERVICE RECORD

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
Line #2 0+00	152.5	148.1	4.4	Existing m.H.								
1+00	155.0	149.1	5.9									
2+00	156.9	150.1	6.8									
3+00	158.2	151.1	7.1									
4+00	158.2	152.1	6.1	4+00								
Line #29 Line #28 Line #2C Line #2D Line #3 Line #4	No informations on grades and dimensions of sewers are available in the plan.				No informations on "Y's" are available							
As found by Sewer Maintenance, Nov. 1982												
	153.70	150.76	2.9	0+87.5	Line N. of Menlo							
	153.37	150.16	3.2	0+92	Line S. of Boston							
					Line #2							
	152.63	143.74	8.9	0+00								
	155.13	146.95	8.2	2+47.3								
	157.63	150.32	7.3	3+93.8								
2001-00789-4/6/01-4233 Boston - McCullings - Donut 137.3' S of mH 2+47.3 (1700) 4" SCH40 ITWING CO, 1045, Fernco to CI @ house - s/o 2001-03066 12/3/01-4214 E Boston - Bammes - ITWING CO 4" SCH40 Tap 34.7' S of mH 0+00												

#92-6799-7 (4236 E. Boston) 5/8/92 - 5/8 4" Clay - one at 150 feet and one at 180 feet. 5 feet of man
 #92-13027-1-31-92 (4201 66th E. Boston) 6-1-92, No Inspection Requested.

5/0 4209 E Boston 5/0 96-6469 - Henning - 4" Clay slo edge of curb 35' E of mH 0+00
 E. side of Boston