



LATERAL 40 SUB. 5 S.S. 22  
 UTILITY CONTR. INC. 1-22-59  
 BK. NO. K-49 PROJ. NO. C28-23

### CONSTRUCTION RECORD

### SERVICE RECORD

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
LINE #1 22+00	123.8	116.00	7.8		+25 <sup>2</sup>	+23 <sup>2</sup>	61858 B 1718		62471 Hoover		4-16-64	
					+74 <sup>0</sup>	+72 <sup>0</sup>						
23+00	123.3 123.2	116.16 116.20	7.1 7.0	22+80 <sup>4</sup>								
					23+21 <sup>3</sup>	+19 <sup>3</sup> +25 <sup>4</sup>	B2490	11599	636 N Hoover 635 N Hoover	see below	12-14-64	10-6-59
24+00	122.7	116.40	6.3		4" SCH 40 24+10 <sup>0</sup>		2001-00465 B1864		630 N Hoover 638 N Hoover	see below	3-5-61 8-31-64	
25+00	122.3	116.60	5.7		24+63 <sup>0</sup>	+65 <sup>0</sup>	96-112127 15846				7-15-62 7-3-62	
26+00					25+25 <sup>2</sup>	+23 <sup>2</sup>	21274 7086		552510 Central		9-1-88 7-29-58	
	123.6	116.82	6.8	26+10 <sup>0</sup>								
LINE #1A 0+00	121.6	114.38	7.2	Existing M.H.								
1+00	122.1	114.58	7.5									
					+13' (K.N.)		10163		500 N Hoover		4-27-59	
122.6	114.66	7.9	1+40 <sup>3</sup>									
LINE #1B 0+00	123.6	116.96	6.6	Existing M.H.								
1+00	123.3	117.12	6.2									
	123.3	117.22	6.1	1+50 <sup>0</sup>								
LINE #1C 0+00	123.5	116.96	6.5	Existing M.H.			072345-7 11868				5-7-77 11-17-59	
	123.6	117.11	6.5	0+93 <sup>0</sup>			20031629		643 N Hoover 551 N Hoover Central	N/C	7-14-50	
LAT. 40 SUB. 5 0+00	116.1	104.50	11.6	Existing M.H.								
					+675 <sup>AP</sup>	+65 <sup>6</sup>	C17803	C24386	3705 3703 510 S Hoover McComas	3703 371 510 S Hoover McComas	1-30-70 7-16-55	8-12-72 2-5-59
1+00	115.6	104.90	10.7		0+82 <sup>AP</sup>	+78 <sup>5</sup>	14696	9311				
					1+25 <sup>5</sup>	+83 <sup>5</sup>			511 S Hoover 519 S Hoover			10-4-78 9-26-69
2+00	115.3	105.30	10.0		2+12 <sup>0</sup>				521 Hoover Kessler			12-22-88
					2+19 <sup>2</sup>		B2235					
3+00	114.4 114.2	105.70 105.78	8.7 8.4	3+20 <sup>3</sup>	2+86 <sup>3</sup>	2+84 <sup>8</sup>	1854	61183	526 Hoover McComas	587 Hoover	11-26-64 1-13-62	5-1-61
4+00	114.2	106.10	8.1		+43 <sup>0</sup>	+41 <sup>0</sup>	11252	10431	532 S Hoover McComas	533 S Hoover Kessler	8-24-59	5-28-59
5+00	113.7	106.50	7.2		+32 <sup>0</sup>	+30 <sup>0</sup>	13655	#3961	534 S Hoover McComas	537 S Hoover Kessler	11-29-60	8-18-61
					+62 <sup>2</sup>							
6+00	114.1	106.90	7.2		4+72 <sup>2</sup>			9149		545 Hoover Kessler		1-20-59
					5+28 <sup>2</sup>	+26 <sup>2</sup>	C48403	9150	542 S Hoover McComas	549 Hoover Kessler		1-20-59
7+00	113.9	107.06	6.8	6+41 <sup>0</sup>	TAP 5+94 <sup>6</sup>	+87 <sup>4</sup>		25786	548 S Hoover McComas	601 Hoover Kessler	7-2-71	11-17-67
	113.9	107.06	6.8		+17 <sup>4</sup>							
8+00	114.9	107.70	7.2		+49 <sup>2</sup>	6+47 <sup>2</sup>		1876 14027		603 Hoover Kessler		1-21-92 4-3-61
					+45 <sup>0</sup>		B6408 7312 C41486	6919 Hoover	605 Hoover Kessler		9-28-66 2-5-54	11-4-82
9+00	116.7	108.10	8.6		7+51 <sup>0</sup>							
					+07 <sup>0</sup>	+05 <sup>0</sup>	9304	11952	612 Hoover McComas	see below	10-2-73	
					+37 <sup>0</sup>		9303		614 Hoover McComas	616 Hoover Kessler	2-4-59	12-2-59
					+71 <sup>0</sup>		15927 13012 #B76	70% Hoover	614 Hoover McComas	617 Hoover Kessler	2-4-59 7-20-62	11-1-60 6-20-60
10+00	115.8	108.30	7.5	9+50 <sup>0</sup>	+89 <sup>2</sup>				622 Hoover McComas		8-26-63	
					+44 <sup>3</sup>							

2001-01005-42661-612 S McComas - Bourers - 4" SCH 40 Soil Pipe Ext - 17WINCO  
 2001-00465-35101-630 N Hoover - Noah NoLeaks - 4" SCH 40, Tied 2' from main to claytile, 2 Twinco, 3V45, 1-4" Y

11289  
 #14134 top 629 S. Kessler - Hoover - 5-1-61 (9+33.0)  
 #16376 top 630 S. McComas - Hoover - 11-19-62 (9+50 m.h.)  
 92-5757-7 42492 - 635 N Hoover (New House Sewer to tie into exist. Bldg Sewer) Richardson Pk.  
 92-636-7 42492 635 N Hoover (Orig House sewer to be sealed off from New House sewer)  
 appears to be address my up - this move in house was for  
 510 S McComas - address my up - this move in house was for  
 2 and should have address of 518 S. McComas -