



SPOT REPAIR
15' 8" VCP
1986

SPOT REPAIR
10' 10" VCP
1986

Minor Lane
Plan to add
Private for
55' x 100' plus
872

Scale 1" = 200'



LAT. C-5, C-5-A, C-5-B, C-5-C, C-5-C-1, C-5-C-2
 COUNTRY ACRES IMPROVEMENT DISTRICT
 FLOYD B. DEVLIN, ENG. - UTILITY CONTRACTORS, INC.
 CONSTRUCTION DATE 1955 - BOOKED 1962

CONSTRUCTION RECORD

SERVICE RECORD

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS		
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East	
LAT. C-5-C													
0+00	15.8	11.42	4.4	Exist. 0+00	1+05.6		C45799		1102			7-17-74	
1+00	15.9	11.82	4.1		1+55.9	(1+19.8)	C44384	C21157	Summitlawn	1101	Sandplum	4-18-74	9-30-70
2+00	16.2	12.22	4.0			(2+41.4)	Tap C32480		1110	1109	Sandplum		5-26-72
3+00	17.0	12.62	4.4		2+27.6		C26188		Summitlawn			8-5-71	
4+00	20.8	13.02	7.8		2+98.0	3+26.6	C30574	C30062	Summitlawn	1113	Sandplum	2-22-72	1-19-72
	22.0	13.04	9.0	4+06.0	3+80.3	4+32.4	C34266	C27825	Summitlawn	1117	Sandplum	8-15-72	9-13-71
5+00	25.0	14.80	10.2		4+54.2	4+78.4	C34265	C30932	Summitlawn	1121	Sandplum	8-15-72	3-13-72
6+00	29.0	16.67	12.3		5+50.0	5+75.9	C44382	C35362	Summitlawn	1125	Sandplum	4-10-74	10-12-72
7+00	31.1	18.54	12.7		6+16.0	6+16.0	C44383	C35363	Summitlawn	1129	Sandplum	4-10-74	10-12-72
8+00	32.6	20.41	12.2		6+90.6	7+32	C44384	C35364	Summitlawn	1133	Sandplum	4-10-74	10-12-72
	32.6	20.64	12.0	8+13.0	7+83.7		C44385		Summitlawn			4-10-74	
9+00	34.0	21.00	13.0		10+53.2		C57544		Summitlawn			3-2-73	
10+00	34.2	21.40	12.8			12+41	99-0118	C37545	Summitlawn	1208	Mulberry	11-5-77	3-2-73
11+00	34.2	21.80	12.4			11+24.2	C54968		Summitlawn	1203	Mulberry		4/26/76
	34.2	21.94	12.3	11+38.0		11+93.8	C40329		Summitlawn	1209	Mulberry		7-31-73
12+00	34.5	22.19	12.3		11+93.9		C18107		Summitlawn	1216	Mulberry	2-24-70	
13+00	34.6	22.59	12.0		12+87.6	13+20.5	94-10944	C37546	Summitlawn	1224	Mulberry	7-7-94	3-2-73
14+00	34.8	22.99	11.8						Summitlawn	1240		10/20/70	
15+00	35.0	23.39	11.6		15+80.5		C40334		Summitlawn	1256		7-31-73	
16+00	35.0	23.79	11.2		17+23.6		C4275		Summitlawn			8-7-67	
17+00	35.0	24.19	10.8										
18+00	35.0	24.59	10.4		18+01.0		C30336		Summitlawn			2-7-72	
19+00	35.0	24.99	10.0		18+65		C2482		Summitlawn	1308	Mulberry	10-05-71	
20+00	35.0	25.39	9.6		20+30		C11412		Summitlawn	1340		11-13-68	
21+00	35.0	25.79	9.2		21+02		C15280		Summitlawn	1348		8-6-69	
	35.0	25.88	9.2		21+36		C12893		Summitlawn	1379		2-25-69	
22+00	35.0	26.29	8.7		22+61.6	21+82.0	C27920	C27826	Summitlawn	1384		4-24-67	1-4-72
23+00	35.0	26.69	8.3		23+39.6		C22981		Summitlawn	1333		2-17-71	
	35.0	27.00	8.0	23+77.0	23+33.6		C23142		Summitlawn	1387		3-12-71	
					manhole-top		C24764		Summitlawn	1303		6-7-71	
LAT C-5-C-1													
0+00	35.0	23.34	11.7	Exist. 0+00	0+72		C-22942	C37547	7021 W	1223	Mulberry	2-16-71	3-2-73
1+00	35.2	23.74	11.5		1+34	1+92.0	C28786		7015	1207	Mulberry	?	10-24-71
2+00	35.5	24.14	11.4		2+25.3		C39435		7007	1204	Mulberry	7-2-68	
	35.6	24.32	11.3	2+45.0	2+81.6		C25256		7012	1231	Mulberry		6-23-71
3+00	35.8	24.54	11.3		3+57.7		C67402		7011	1235	Mulberry		7-12-78
4+00	35.8	24.94	10.9				C42332		1201	1213	Mulberry	11-20-73	
	34.9	25.30	9.6	4+90.0			C42333	C40257	1201	1213	Mulberry	11-20-73	7-25-73
5+00	34.8	25.44	9.4		5+84	5+35.8	C21596	C48392	1206	1219	Sandplum	11-2-70	2-14-75
6+00	34.2	25.84	8.4		7+04.4	5+92.8	C21742	C47609	1312	1225	Sandplum	11-11-70	12-2-74
7+00	34.1	26.24	7.9		6+65.8		C47603		1304	1305	Sandplum		12-2-74
8+00	33.4	26.64	6.8		7+81	8+30.4	C2476	C47604	1318	1305	Sandplum	6-7-71	12-2-74
9+00	33.5	27.04	6.5		8+62	8+90.6	C21597	C47605	1310	1311	Sandplum	11-2-70	12-2-74
	33.6	27.06	6.5	9+06.0									
10+00	33.4	27.54	5.9		9+48.0	9+93	C28801	C47606	1330	1317	Sandplum	11-1-71	12-2-74
	34.6	27.68	6.9	10+36.0	4" Stake	10+18.2	C30061	C47607	1326	1326	Sandplum	1-19-72	12-2-74
LAT C-5-C-2													
0+00	35.0	24.66	10.3	Exist. 0+00	0+27		C6761		1323	1316	Sandplum	2-6-68	See Janing
	36.0	25.08	11.0	0+79.0	1+23.5		C3967		1224	1224	Sandplum		8-20-81
1+00	36.0	25.16	10.8		1+85		C616526		1300	1324	Sandplum		10-28-69
2+00	37.0	25.59	11.3	2+02.0	2+16		C6761		1311	1311	Sandplum		3-29-68
3+00	36.0	26.08	9.9		3+28.5	3+04	C12680	C25458	1328	1321	Sandplum	2-4-69	7-13-71
	36.0	26.37	9.6	3+72.0	3+63		C22980		1327	1327	Sandplum		

Tap C49696-1303 Sandplum - 7/29/75 - D.M. Hardworth (9+44)
 Tap C52376-7015. Buarwood - 11-10-75 - Bob Scott (21+88) 99-00858 10-7-99 1133 N Sandplum -
 94-10944-0701 - 1224 N Summitlawn - Repair

7015 W 12th - sewer main Reunard their TU logs - advised TAP at 1134
 there is wire at 113 - but believe TAP is conn. point.

SWR 2001-02482-1816 Semmitlow¹⁰⁵¹⁰ - Rotb Rostr - City Wye repair 736' N of MH 17192 (18165) 4" PE SDK 17 Pipe Burst
Replacement 1-6" Aradco, 1122