



Note
 TRAP Reg'd on
 all Lines commencing
 to Mains
 15" and Larger
 per sewer Maint.
 BSR
 92401

↑
 1" = 200'

Trap Reg'd
 439
 Washfield
 confirmed
 by simulators +
 line for 439 west field
 744 C. Foght
 sewer Maint

See Plat
 For Util.
 F.S.M.#
 9109108
 BSR

**SANITARY SEWER SYSTEM
 WESTLINK VILLAGE
 SEDGWICK COUNTY KANSAS**

H.R. HUNTER - CONSULTING ENGINEER

WICHITA, KANSAS - 3-7-1955

BOOKED FROM FINAL PLAN - 1-15-1963

NOTE: SEA LEVEL ELEVATIONS

CONSTRUCTION RECORD						SERVICE RECORD						
STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
LAT. #6												
0+00	1330.0	out 1316.55 in 1320.00	13.5 10.0	Exist. 0+00 ^o	0+52 ^o	0+49 ^o	9720987		9621 Hardman		2-18-97	
1+00	30.1	20.60	9.5		0+98 ^o	1+98 ^o						
2+00	30.0	21.20	8.8		2+05 ^o	2+64 ^o	20076322 23275	16423	9711 R Hardman	2-5-02 8-4-86	6-6-86	
3+00	30.6	21.80	8.8		2+67 ^o	3+36 ^o	16422		9710 R Hardman	6-6-86	6-6-86	
4+00	32.3	1322.40	9.9	4+00 ^o	3+39 ^o	3+36 ^o	7455		9711 R Hardman	2-11-83		
5+00	32.7	24.50	8.2		4+50 ^o	4+53 ^o						
6+00	34.0	26.60	7.4		CITY 4454 WIRE 5+80 ^o	5+83 ^o	2001- 00370		9801 W Hardman	See next pg	2-7-01	
7+00	38.2	28.70	9.5		6+68 ^o	6+71 ^o						
8+00	40.0 40.2	1330.42 30.50	9.6 9.7	7+82 ^o	7+50 ^o	7+53 ^o	9644197		9822 R W Tee		4-3-96	
9+00	42.0	30.91	11.1		8+32 ^o	8+35 ^o	052770		9822 R W Tee		10/11/75	
10+00	43.2	1331.37	11.8	10+00 ^o	9+36 ^o	9+42 ^o						
11+00	42.3	31.76	10.5		10+50 ^o	10+53 ^o						
12+00	40.8 40.2	32.18 1332.29	8.6 7.9	12+30 ^o	11+30 ^o	11+33 ^o						
LAT. #7												
0+00	29.5	out 1316.72 in 1319.55	12.8 10.0	Exist. 0+00 ^o								
1+00	29.8	19.95	9.9									
2+00	29.4	1320.31	9.1	1+90 ^o								
3+00	31.0	21.05	10.0		3+74.0 ^o	3+81.0 ^o	12513		9710 Hardman		11-13-84	
4+00	31.0	1321.48	9.5	3+60 ^o	4+00 ^o	4+00 ^o	12572		9710 Hardman		11-13-84	
5+00	31.0	21.65	9.4		4+84 ^o	4+81 ^o						
6+00	32.5	22.07	10.4		5+43 ^o	5+40 ^o	81866		9726 Hardman		8-21-64	
7+00	34.5	1322.45	12.1	5+90 ^o	6+06 ^o	6+09 ^o						
8+00	34.0	22.48	11.5		7+80 ^o	7+83 ^o	6321		9901 Binter	8-10-82		
9+00	35.5	22.85	12.7		8+42 ^o	9+06 ^o	22290		9911 Binter	12-27-88		
10+00	38.0	23.22	14.8		9+10 ^o	9+97 ^o	22278		9911 Binter	12-22-88		
11+00	40.1 40.5	1323.51 23.63	16.6 16.9	8+75 ^o	9+88 ^o	9+97 ^o						
12+00	41.0	24.11	16.9									
13+00	40.8	1324.18	16.6	10+14 ^o								
14+00	40.0	24.52	15.5		11+70 ^o							
15+00	39.0	24.92	14.1		12+70 ^o		25021		9905 Binter	5-17-83		
16+00	37.2	25.32	11.9									
17+00	37.5	1325.34	12.2	13+06 ^o	13+55 ^o		26717		550 B Valleyview	12-11-90		
18+00	38.1	25.75	12.4		14+78 ^o							
19+00	38.5	26.18	12.3		15+54 ^o		8177		601 R Clipperton	5-17-83		
20+00	38.2	26.62	11.6		16+30 ^o		8178		609 R Clipperton	5-17-83		
21+00	38.4	1327.05	11.4	17+00 ^o								

669010 - Repair 301 Sarway - Herring 10-20-78 (6+26.7)
 R 5811-9840 Tee Lane 5-10-82 Van White 10+00-0 E (8+78.1)(96.1W of MH 7+82.0)
 R 22278-9911 W. Binter - 12-22-88 - Jess McCullough

2002-00322-21562- 9711 W Hardtner - Always P169- 4" SCH40- Donut to wye (m smt good) 1V45, 1TW100, 1Fernco to CI @ house

2001-20270-21700 - 9801 W Hardtner - Morris Ditch - 4" SCH40 City Repair 4" Predco 180' W of Mt 4100 (5+80) 1TW100, Fernco to CI @ house, 1V45, 2H45

2000-01743 7/28/00 542 N Valleyview - Wichita EX - 4" SCH40 (0+16) Tied to claytile - 1 Twin 60, 1H22+1H45