

Checklist

- 1 Clean underdrain screens West end of Filter Building.
- 2 Inspect, flush and test CP/EP Sludge Transfer Station sump pits
- 3 Perform Moyno pump Daily Screen PM
- 4 Inspect, flush and clean out Sludge Plant sump pits
- 5 Floc Room Sump Pit Flush and Clean out.
- 6 Tank Farm Sump Pits Flush and Clean Out
- 7 O/L Lime Slaker; Clean Arrestor, Tube, Nozzles, SAT Air Vent on Tank, Grit Basket lid, seat, closure
- 8 CP/EP Sludge Recycle Pumps Clean and Inspect Equipment and area.
- 9 Ferric Screen PM; Chemical Feed Pumps on EP/CP and Bulk Tank Transfer Pump
- 10 Grit Auger, Flush &/or Rod out Down Pipe. Auger Flush "Acid Magic" and dumpster areas clean up.
- 11 Walk thru inspection of Lime system, shaker room, lime bin area, Slaker Room. Report all concerns
- 12 EP Boiler Recirc Pump switch over. Note in-service inlet PSI and outlet PSI
- 13 CP Raw Water Line Flush
- 14 Review Chlorine and Ammonia Tank Levels, Review temperature and Vaporizer needs. Report any concern.
- 15 Clarif. PM; Drive Ass. noise, chain tens. motor fan, torque read. Drain Pri. Housing, Top off Lube.
- 16 Test and Inspection of boilers when in service
- 17 Lime Slaker Rm Ventilation: Clear inlet and outlet vents, inspect blower ops, pulleys and belts
- 18 Walk all chemical feed pump areas: inspect equipment. Check bins for spare parts. Maintain inventory
- 19 Weekly Rotation of air Compressors, Unit in service, out of service
- 20 Check Grease Cartridges for Auto Greasers on Lime System 4th Flr. Date cartridges.
- 21 Inspect, flush and clean out Pipe Gallery sump pits East & West
- 22 CP Chiller Pumps - Rotate
- 23 Resolve concerns and/or make Lucity WO on ALL issues not resolved and needing addressed.