

5410WTP1MME106 Monthly MWTP PM Equipment Greasing Schedule

Checklist

- 1 1 shot MP grease into sludge return pump bearings in flocculator room
- 2 In Central Plant Basin Clarifiers, Grease drive shaft bearings with 1 shot MP grease
- 3 In Central Plant Basin Clarifiers, Brush drive chains with chain lube
- 4 Straight Line Collectors, grease sprocket hubs (where shear Pins) with 2 shots of MP grease
- 5 Check Straight Line Collector mounting bolts for tightness
- 6 Pipe Gallery, flush lines on CP influent and clearwell, EP final settling and clearwell sample pumps
- 7 Add 1 shot MP grease to Wash Water Pumps in Pipe Gallery
- 8 Flush Sump Pump Pits in CP and EP
- 9 Sludge Transfer Station Transfer Pumps, 1 shot MP grease into pump bearings
- 10 In PRV Vault, 1 shot MP grease into Bailly Valve Screws
- 11 On Contact Basin Sample Pumps, backflush Lines
- 12 At Sludge Plant, 1 shot MP grease to disposal pumps
- 13 EP Clarifiers when in service, spray drive chain with chain lube
- 14 EP Sludge Return Pumps 1 shot MP grease to bearings