



B.M. 97.30 S.E. Cor. Conc. Patch No. #1502 W. 30th St. So.
 B.M. 98.21 S.E. Cor. Conc. Patch No. #3015 Elizabeth
 B.M. 99.02 S.E. Cor. Conc. Patch No. #2915 Elizabeth
 B.M. 99.13 S.W. Cor. 1st Step No. #1206 W. 27th St. So.

Stationed on W. Line of Elizabeth




NOTE TO FIELD ENGINEER & CONTRACTOR—
 The drives on the East side of Elizabeth have
 to be reinforced. See detail at right.




STEEL REINF. FOR DRIVES EAST SIDE ELIZABETH
 NOT TO SCALE

ELIZABETH ST.
 S.L. OF REPLAT BLKS. B, C, & D
 PANVRANTZ 2ND ADD - S.L. REGAL
 30' CONC. & C.B.
 CITY OF WICHITA, KANS.
 B.E. SMITH CITY ENGINEER
 JAN., 1955 PROJ. NO. C14-30



1/6



ELIZABETH ST
PROJ. NO. C14-50