

COORDS IRON

Point #	Northing	Easting	Raw Description
1	7633.84	17275.96	iron
2	7782.42	17604.37	iron
3	7781.48	17545.70	iron
4	7845.64	17555.35	iron
5	7845.47	17544.67	iron
6	7895.13	17495.93	iron
7	7897.34	17431.97	iron
8	8110.85	17503.39	iron
9	8114.04	17702.88	iron
10	8172.82	17751.31	iron
11	8168.89	17505.40	iron
12	8372.53	17512.45	iron
13	8374.74	17448.48	iron
14	8482.86	17561.57	iron
15	8418.86	17560.91	iron
16	8480.16	17824.06	iron
17	8416.17	17823.40	iron
18	8430.92	17907.24	iron
19	8490.85	17884.77	iron
20	8498.77	17905.89	iron
21	8438.84	17928.36	iron
22	8513.69	17905.04	iron
23	8513.73	17969.04	iron
24	8465.66	17988.98	iron
25	8420.37	17943.76	iron

COORDS SWS

Point #	Northing	Easting	Raw Description
7000	7666.36	17737.22	0+00
7001	7663.44	17555.25	1+82.0
7002	7804.16	17771.57	0+00
7003	7830.03	17641.65	1+32.5
7004	8103.96	17959.79	0+00
7005	8121.61	17790.24	1+70.5

