



COORDS WATER

Point Table			
Point #	Northing	Easting	Raw Description
6000	1651887.00	1630702.58	0+00
6001	1651886.61	1630573.58	1+29
6002	1651937.61	1630573.43	1+80
6003	1651937.24	1630448.43	3+05
6004	1651936.85	1630320.38	4+33.05
6005	1651991.15	1630193.14	5+75.27
6006	1652050.68	1630136.44	6+57.48
6007	1652091.56	1630097.49	7+13.95
6008	1652130.35	1630007.00	8+15.15
6009	1652130.36	1629902.61	9+19.53
6010	1652225.97	1629904.65	10+15.16
6011	1652253.51	1629906.94	10+42.82
6012	1652282.82	1629913.24	10+72.82
6013	1651746.61	1630574.00	1+40
6014	1651683.53	1630574.19	2+03.09
6015	1651666.75	1630557.52	2+26.74
6016	1651633.84	1630557.62	2+59.66
6017	1651610.64	1630580.96	2+92.57
6018	1651610.74	1630613.87	3+25.48
6019	1651634.08	1630637.07	3+58.39
6020	1651677.08	1630636.94	4+01.39
6021	1652079.36	1629901.53	0+51.01
6022	1652079.37	1629800.05	1+52.49
6023	1652065.71	1629786.39	1+71.81
6024	1652065.60	1629748.90	2+09.29
6025	1652093.86	1629720.48	2+49.38

COORDS IRON

Point Table			
Point #	Northing	Easting	Raw Description
1	1652331.10	1629868.90	iron
2	1652306.16	1629927.84	iron
3	1652225.85	1629910.65	iron
4	1652227.21	1629846.67	iron
5	1652137.37	1629844.75	iron
6	1652137.36	1629908.76	iron
7	1652137.37	1629803.66	iron
8	1652073.37	1629803.66	iron
9	1652073.35	1630006.99	iron
10	1652137.35	1630007.00	iron
11	1652096.39	1630102.56	iron
12	1652052.25	1630056.22	iron
13	1651951.83	1630151.87	iron
14	1651995.98	1630198.21	iron
15	1651943.85	1630320.36	iron
16	1651879.85	1630320.55	iron
17	1651945.05	1630717.14	iron
18	1651881.05	1630717.33	iron
19	1651903.77	1630832.33	iron
20	1651963.03	1630808.16	iron
21	1651880.77	1630625.60	iron
22	1651880.60	1630567.60	iron
23	1651691.06	1630568.17	iron
24	1651691.23	1630626.17	iron
25	1651434.36	1630760.26	iron
26	1651524.37	1630434.85	iron
27	1651743.73	1630434.56	iron
28	1651743.63	1630159.56	iron
29	1651933.58	1630159.31	iron
30	1651933.40	1629669.31	iron

