



BENCHMARKS

BM #1: Brass Plate on North  
Hub Guard of R.C.B.C. 50' East of  
NW Corner NE 1/2, Sec. 22, Twp.  
26-S, R-1-E.  
Elev. = 1371.83 (NGVD29)


BM #2: "X" cut on East Hub  
Guard of R.C.B.C., 110' S. of the  
SE Cor., SE 1/4, Sec. 22, Twp.  
26-S, R-1-E.  
Elev. = 1359.54 (NGVD29)



SEWER SERVICE TABLE

| NUMBER | TYPE               | LOCATION |           |          | FOR INFORMATION ONLY |                                                   |
|--------|--------------------|----------|-----------|----------|----------------------|---------------------------------------------------|
|        |                    | LOT NO.  | BLOCK NO. | LINE NO. | STATION DIRECTION    | APPROXIMATE LENGTH 4" PIPE<br>VERTICAL HORIZONTAL |
| 38     | 8" x 4" Tee Saddle | 48       | E         | 3        | 3+22/Rt.             | 7.5' 15'                                          |

NOTE: Vertical Riser Pipe shall be extended to 2' minimum above ground water elevation and 4' maximum below proposed ground elevation.





Falcon Falls 2nd Addition

**LINE 3**

SANITARY SEWER IMPROVEMENTS

Baughman Company, P.A. 315 Ellis St., Wading, KS 67111 P:316-262-7171 F:316-262-0149

ENGINEERING | SURVEYING | PLANNING | LANDSCAPE ARCHITECTURE

PROJECT NUMBER  
468-84063

DESIGN  
TJW

APPROVED  
AEG

REVISIONS

DATE  
10/05/05

SCALE  
Noted

SHEET  
**13 OF 32**

F:\eng\Falcon Falls 2nd\SS\ss012.dwg

05-08-1344