

4+08.03

R/W

R/W

1325

1320

1315

-50

-45

-40

-35

-30

-25

-20

-15

-10

-5

0

5

10

15

20

25

30

35

40

45

50

1320.1  
1318.92

3+50

1325

1320

1315

-50

-45

-40

-35

-30

-25

-20

-15

-10

-5

0

5

10

15

20

25

30

35

40

45

50

1319.7  
1318.84

3+00

1320

1315

-50

-45

-40

-35

-30

-25

-20

-15

-10

-5

0

5

10

15

20

25

30

35

40

45

50

1319.7  
1318.70

2+50

1325

1320

1315

-50

-45

-40

-35

-30

-25

-20

-15

-10

-5

0

5

10

15

20

25

30

35

40

45

50

1319.8  
1318.87

2+00

1325

1320

1315

-50

-45

-40

-35

-30

-25

-20

-15

-10

-5

0

5

10

15

20

25

30

35

40

45

50

1319.8  
1319.05

1+50

1325

1320

1315

-50

-45

-40

-35

-30

-25

-20

-15

-10

-5

0

5

10

15

20

25

30

35

40

45

50

1320.2  
1319.22

1+00

1325

1320

1315

-50

-45

-40

-35

-30

-25

-20

-15

-10

-5

0

5

10

15

20

25

30

35

40

45

50

1320.2  
1319.40

0+50.02

1325

1320

1315

-50

-45

-40

-35

-30

-25

-20

-15

-10

-5

0

5

10

15

20

25

30

35

40

45

50

1320.1  
1319.57

