


SEE SH. C5.1 FOR SITE TEMPORARY EROSION CONTROL

SEE SH. C5.2 FOR EROSION CONTROL DETAILS

- LEGEND**
- SILT FENCE
 - DITCH CHECK



WILSON & COMPANY
 Engineers & Architects

1700 East Iron - Salina, Kansas 67401
 Tel 785 - 827-0433 Fax 785 - 827-5949

FACILITY IMPROVEMENTS
CIRCLE UNIFIED SCHOOL DISTRICT U.S.D. NO 375
GREENWICH ROAD
NEW ELEMENTARY SCHOOL

DESIGN	JCK
DRAWN	CJT
DATE	06/09
FILE NO.	08-500-037-00
SHEET NO.	C2.5