

14+90.64

1350 1950

1340 1940

1340.67  
1340.67

1350 1950  
-40 -30 -20 -10 0 10 20 30 40

14+50.00

1350 1950

1340 1940

1340.32  
1340.32

1350 1950  
-40 -30 -20 -10 0 10 20 30 40

14+00.00

1350 1950

1340 1940

1339.76  
1339.76

1350 1950  
-40 -30 -20 -10 0 10 20 30 40

13+50.00

1350 1950

1340 1940

1339.01  
1339.01

1350 1950  
-40 -30 -20 -10 0 10 20 30 40