



IRONS

Point #	Northing	Easting	Raw Description
1	4995.17	5951.79	iron
2	4994.87	6009.79	iron
3	4951.30	6009.57	iron
4	4951.59	5951.57	iron
5	4871.17	5942.33	iron
6	4858.31	5998.88	iron
7	4809.55	5987.79	iron
8	4822.42	5931.23	iron
9	4725.31	5920.55	iron
10	4725.57	5978.55	iron
11	4625.57	5979.00	iron
12	4625.31	5921.00	iron
13	4528.30	5932.57	iron
14	4541.68	5989.00	iron
15	4493.03	6000.54	iron
16	4479.65	5944.10	iron
17	4395.71	5954.10	iron
18	4395.97	6012.10	iron
19	4322.52	6012.42	iron
20	4322.27	5954.43	iron
21	4247.38	5988.69	iron
22	4215.46	6008.55	iron
23	4162.64	5923.63	iron
24	4194.57	5903.78	iron
25	4206.49	5825.90	iron
26	4258.40	5851.76	iron
27	4558.38	5249.71	iron
28	4506.47	5223.84	iron
29	4699.48	5127.70	iron
30	4688.85	5184.72	iron
31	4787.97	5203.19	iron
32	4845.92	5212.81	iron
33	4844.52	5487.54	iron
34	4786.53	5487.25	iron
35	4822.40	5150.61	iron
36	4903.16	5158.28	iron
37	4902.86	5216.28	iron
38	4998.90	5216.77	iron
39	4999.19	5158.77	iron
40	5000.00	5000.04	iron
41	4479.41	5002.34	iron
42	3913.94	6137.24	iron
43	4994.25	6132.45	iron

WATER DIST. SYSTEM

Point #	Northing	Easting	Raw Description
6000	4379.45	5960.17	0+00
6001	4395.74	5960.10	0+16.29
6002	4481.03	5949.94	1+02.37
6003	4529.68	5938.40	1+52.37
6004	4625.34	5927.00	2+48.91
6005	4725.34	5926.55	3+48.91
6006	4821.09	5937.09	4+45.45
6007	4869.84	5948.18	4+95.45
6008	4951.56	5957.57	5+77.87
6009	4999.17	5957.81	6+25.48
6010	5005.14	5957.84	6+31.45
6011	5034.49	5957.99	6+60.80

