

Signed Chris Copeland Contractor PHILLIPS SOUTHERN ELECTRIC Date 6/16/08

Project TRAFFIC SIGNALIZATION @ N. I-235 AND MERIDIAN INTERCHANGES

Project Number 472.84424 (706956) * SOUTH INTERSECTION *

1) MOVED SIGNAL POLE BASE @ SW COR. OF SOUTH INTERSECTION APPROX. 4' S. OF PLAN. (POLE BASE @ PLAN LOCATION HAD INCORRECT BOLT PATTERN).

2) TRAFFIC CONTROLLER PAD MODIFIED TO BETTER SUIT SITE CONDITIONS
(SEE BACK)

3) MAST ARM ON POLE @ SW COR HAS A "DOG LEG" BEAM IN IT. BENT DURING SHIPMENT; APPROVED FOR USE BY PAUL GUNZEL, MAINT. TRAFFIC ENG.

Form 192-034 (4/81)

Signed Chris Copeland Contractor PHILLIPS SOUTHERN ELECTRIC Date 6/16/08

Project TRAFFIC SIGNALIZATION @ NORTH I-235 AND MERIDIAN INTERCHANGES

Project Number 472.84424 (706956) * NORTH INTERSECTION

1) SIGNAL POLE @ NE COR OF INTERSECTION MOVED APPROX. 5' S. AND 3' WEST. (POLE BASE @ PLAN LOCATION HAD INCORRECT BOLT PATTERN).

2) TRAFFIC MH MOVED APPROX. 10' EAST AND 5' NORTH OF PLAN TO GET MH AWAY FROM ASPH. SHOULDER

3) TRAFFIC CONTROLLER AND PAD MOVED APPROX. 28' NORTH OF PLAN. IT WAS MOVED TO N. SIDE OF NEW SIGNAL POLE AS A PRECAUTIONARY MEASURE.

Form 192-034 (4/81)

Sketches, etc.

CONTROLLER BOX

ASPHALT
SHOULDER

PAD NARROWED
FROM FRONT TO BACK

LESS FILL DIRT REQUIRED

EXISTING GROUND

Signed Chris Cokendall Contractor PHILLIPS SOUTHERN ELECTRIC Date 6/16/08

Project TRAFFIC SIGNALIZATION @ N. I-235 AND MERIDIAN INTERCHANGES

Project Number 472.84424 (706956) * SOUTH INTERSECTION *

1.) MOVED SIGNAL POLE BASE @ SW COR. OF SOUTH INTERSECTION APPROX. 4' S. OF
PLAN. (POLE BASE & PLAN LOCATION HAD INCORRECT BOLT PATTERN)

2.) TRAFFIC CONTROLLER PAD MODIFIED TO BETTER SUIT SITE CONDITIONS
(SEE BACK)

3.) MAST ARM ON POLE @ SW COR HAS A "DOG LEG" BECAUSE IT WAS BENT
DURING SHIPMENT; APPROVED FOR USE BY PAUL GUINZEL MAINT. TRAFFIC ENG.

ENGINEERING DEPARTMENT

CITY OF WICHITA

MISCELLANEOUS INFORMATION

Signed Chris CopelandContractor PHILLIPS SOUTHERN ELECTRICDate 6/16/08Project TRAFFIC SIGNALIZATION @ NORTH I-235 AND MERIDIAN INTERCHANGESProject Number 472.84424 (706956) * NORTH INTERSECTION

- 1) SIGNAL POLE @ NE COR OF INTERSECTION MOVED APPROX. 5'S AND 3' WEST.
(POLE BASE @ PLAN LOCATION HAD INCORRECT BOLT PATTERN).
- 2) TRAFFIC MH MOVED APPROX. 10' EAST AND 5' NORTH OF PLAN TO GET MH AWAY FROM
ASPH. SHOULDER
- 3) TRAFFIC CONTROLLER AND PAD MOVED APPROX. 28' NORTH OF PLAN. IT
WAS MOVED TO N. SIDE OF NEW SIGNAL POLE AS A PRECAUTIONARY
MEASURE.

Sketches, etc.

CONTROLLER BOX

ASPHALT
SHOULDER

PAD NARROWED
FROM FRONT TO BACK

LESS FILL DIRT REQUIRED

EXISTING GROUND

ENGINEERING DEPARTMENT

CITY OF WICHITA

MISCELLANEOUS INFORMATION

Signed Tim AnthisContractor PSEDate 4-14-08Project 06/07 Traf. Signalization - Ph IProject Number 472-84424 (706956)

No major changes except for minor movements
of signal pole bases & realignment of sidewalks
— Additional New style WCR's added @
13th str. site per ADA standards