

**Attachment A Locations 2011 CM Asphalt and Concrete Preparatory Work & Repairs**
**472-84961 (132724)**

<i>Street</i>	<i>From</i>	<i>To</i>	<i>Project</i>	<i>CCD</i>	<i>CL</i>	<i>L FT</i>	<i>W FT</i>	<i>Surface</i>	<i>Street Prep, SY</i>	<i>TC Repair, LF</i>	<i>Cb &amp; G LF</i>
<b>Heater Scarification Locations for Street Prep</b>											
Rock	Douglas	Central	Heater Scarification	2	A	2550	82.6	Composite	200	0	
Rock Rd	N of Kellogg Dr (N)	Douglas	Heater Scarification	2.0	A	1600	94	Composite	200		
Maize	Maple	North at Bridge	Heater Scarification	5.0	A	2330	55.0	Asphalt	150	1100	
Willo-Esque	Maple	O'Neil	Heater Scarification	5.6	R	2965	36.0	Asphalt	0		
O'Neil	Willo-Esque	Ridge	Heater Scarification	5.6	R	1195	36.0	Asphalt	0		
55th St S	E of Broadway	Hydraulic	Heater Scarification	3	A	4630	26.0	Asphalt Mat	300		
Zoo Blvd	Central	West St	Heater Scarification	6.0	A	4390	47	Composite	300		
<b>Micro Locations for Street Prep</b>											
Windwood	Rock	Windwood Cir-8103	Micro Surfacing	2.4	R	388	26	Asphalt			
Windwood Cir-8103	Windwood	NE Cul De Sac	Micro Surfacing	2.4	R	315	26	Asphalt			
Windwood Ct-8015	Windwood	S End	Micro Surfacing	2.4	R	220	24	Asphalt	100		
Windwood Ct-8032	Windwood	N End	Micro Surfacing	2.4	R	275	26	Asphalt			
Cleveland	Murdock	13th St	Micro Surfacing	1.0	R	3460	36	Composite	500		
Levitt	Zimmerlay	Lincoln	Micro Surfacing	2.6	R	2240	28	Composite	450		
29th St S	Meridian	Everett	Micro Surfacing	4.0	R	954	28	Composite	300		
Shade Cir-9500	Shade	N Cul De Sac	Micro Surfacing	5.1	R	310	28.0	Asphalt	200		
Shade	Westlink	Fairway	Micro Surfacing	5.1	R	1850	26.0	Asphalt	50		
Crestline	Central	Hardtner	Micro Surfacing	5.2	R	1140	27.5	Asphalt	100		
Hardtner	Maize	Valleyview	Micro Surfacing	5.2	R	1230	27.5	Asphalt	100		
Valleyview	Central	Hardtner	Micro Surfacing	5.2	R	1050	27.5	Asphalt	100		
Binter	Maize	Valleyview	Micro Surfacing	5.2	R	790	27.5	Asphalt	100		
Taylor Cir-10212	Crestline	West End	Micro Surfacing	5.2	R	400	27.5	Asphalt	100		
<b>Add Alternate Locations for Micro</b>											
Bonn	29th St S	30th St S	Micro Surfacing	4-1	R	870	28	Composite	TBD		
Bonn	Pawnee	Hiram	Micro Surfacing	4-1	R	905	28	Composite	TBD		
<b>Thermal Crack Repair Locations</b>											
Nantucket	Hunters View	Coach House	Thermal Crack Repair	5.3	R	100	31	Asphalt	0	155	
Hunters View Ct-12414	Hunters View	W Cul De Sac	Thermal Crack Repair	5.3	R	142	31	Asphalt	0	0	
Hunters View	Coach House	14th St	Thermal Crack Repair	5.3	R	1566	31	Asphalt	0	1240	
Coach House	Hunters View	Nantucket	Thermal Crack Repair	5.3	R	860	31	Asphalt	0	1116	
14th St	Nantucket	Coach House	Thermal Crack Repair	5.3	R	958	31	Asphalt	0	899	
Chateau	119th St W	Coach House	Thermal Crack Repair	5.3	R	240	31	Asphalt	0	93	
Cedar Park Cir-1435	Nantucket	N Cul De Sac	Thermal Crack Repair	5.3	R	170	31	Asphalt	0	217	
Cedar Park	13th St	Nantucket	Thermal Crack Repair	5.3	R	209	31	Asphalt	0	155	
Old Wick	Hunters View	W Cul De Sac	Thermal Crack Repair	5.3	R	209	31	Asphalt	0	527	
53rd St N	Meridian	Arkansas	Thermal Crack Repair	6.0	A			Asphalt		4000	
<b>Add Alternate</b>											
Everett	27th St S	Pawnee	Concrete CG/Drainage Repairs & Asphalt Patch	4.0	R	400		Asphalt	400		6000
<b>Total</b>									<b>3650</b>	<b>9502</b>	<b>6000</b>

CCD= City Council District, CL= Street Class, R= Residential, C= Collector, A= Arterial, TC= Thermal Crack

**Attachment A Locations 2011 CM Asphalt and Concrete Preparatory Work & Repairs**

472-84961 (132724)

Street	From	To	Project	CCD	CL	L FT	W FT	Surface	Street Prep, SY	TC Repair, LF	Cb & G LF
--------	------	----	---------	-----	----	------	------	---------	-----------------	---------------	-----------

