



Standing west of Cleanout 5744-711CO, looking north. There is a garage and trees which may (or may not) be over the sewer line. Contractor has the option of relocating the line if Pipe Reaming or Pipe Bursting is not used. There is no record of where the connections are located. No televising could be done between 5744-712CO and 5744-711CO.



Standing west of Cleanout 5744-713CO, looking east.

Cleanout 5744-713CO is next to the fence at the south property line, under the trees.
Cleanout 5744-714CO is by the house, under a piece of concrete.
We did not find 5744-712CO.

If Contractor chooses to relocate the line between 5744-712 and 5744-711, he may also move the location of 5744-712 to accommodate. Service lines to this building shall be moved accordingly.