

IRONS

Point Table			
Point #	Northing	Easting	Raw Description
1	6759.67	5061.05	iron
2	6689.67	5061.01	iron
3	6760.34	5567.31	iron
4	6690.34	5567.40	iron
5	6778.41	5695.06	iron
6	6711.13	5714.39	iron
7	6816.90	5829.04	iron
8	6749.62	5848.37	iron
9	6929.31	6108.36	iron
10	6867.41	6141.03	iron

Point Table			
Point #	Northing	Easting	Raw Description
11	7015.31	6421.29	iron
12	7112.14	6454.80	iron
13	7034.67	5061.21	iron
14	7028.68	5570.25	iron
15	7115.15	5871.28	iron
16	7486.89	6575.71	iron
17	7523.99	7166.63	iron
18	7438.01	7656.81	iron
19	6313.56	7653.98	iron
20	6310.75	5060.78	iron

SWS

Point Table			
Point #	Northing	Easting	Raw Description
7000	6794.85	5951.66	0+00
7001	6701.87	5592.19	3+71.3
7002	6749.65	5589.86	4+19.1
7003	6994.25	6358.19	4+52.8
7004	7036.56	6335.86	5+00.6

