





BENCHMARKS

BM #1: Brass Plate on North
Hub Guard of R.C.B.C. 50' East of
NW Corner NE 1/2, Sec. 22, Twp.
26-S, R-1-E.
Elev. = 1371.83 (NGVD29)

BM #2: "□" cut on East Hub
Guard of R.C.B.C., 110' S. of the
SE Cor., SE 1/4, Sec. 22, Twp.
26-S, R-1-E.
Elev. = 1359.54 (NGVD29)



Remove trees only as necessary
for sanitary sewer construction
and only with permission of
Developer or Baughman Co.
Cost of removal to be incidental
to lump sum bid item "Site
Clearing & Restoration".



Baughman		Falcon Falls 2nd Addition	
PROJECT NUMBER 468-34065		LINE 7 SANITARY SEWER IMPROVMENTS	
DESIGN TJW		DRAWN TJW	
APPROVED AEO		DATE 10/05/05	
REVISIONS:		SCALE Noted	
SHEET		21 OF 32	
F:\eng\Falcon Falls 2nd SS\ss020.dwg		0508E344	