



2002-00888-3/28/02- 892 S Lexington - Padgett Exc - 4" 40 PVC
 1 twin co, 1V45, 1H45, 4" Wye 21.4' N of MH 0+00 (0+21.4) - Shallow

2001-01686-7/10/01- 814 S Lexington - Roto Rooter - Pipe Burst Replacement 4" PE SDR17
 4" Wye repair - 64.9' S of MH 9+48.7 (8+83.9) Replaced entire line - ITWINCO
 2V22, 1H22, 1H45

2001-01339-6/16/01- 621 S Waverly Dr - Roto Rooter - Pipe Burst Replacement -
 4" PE SDR17 118.7' N of MH 18+45.4 (19+64.1) ITWINCO, 3 KICKDOTS, 1V45 -
 Replaced entire line, Lwr 4" 15" SCH 40 (Tied in 2nd stubout at
 upper end.) Existing co

Rep- 2000-01869- 615 S. Waverly Dr - 8/22/00 - 4" SCH 40, ITWINCO, 2V22, 40 RISER ONLY.
 1 Fernco to clay - 1 Fernco to cast iron, 1 Fernco to plug on exist co

96-3197 1-8-96 6022 E MORRIS - Completed Repl. to Main 10' of 4" PVC 40
 6054 - 6062 E. Lincoln & 875 Fabrique ? TV log shows Tap @ 1+27.5

49010 - 877 Fabrique - Tap 4-14-75 J.C. Severn (2144)

CONSTRUCTION RECORD

SERVICE RECORD

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS	
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East
0+00	147.0	136.99	10.01	0+00 = 3+03.4 in Line #1	0+21.4		# 6 2002-00888		692 - R see next		3-28-52	
1+00	147.7	137.40	10.30		+98.6		# 15		856 R		2-12-52	
2+00	147.9	137.80	10.10		1+59.8		# 14 #3761		850 R		5-15-52	
2+50	147.6	138.00	9.60	2+50	2+33.4		# 13		874 R		2-12-52	
3+00	147.7	138.20	9.50		3+11.5		# 432		868 R		12-8-51	
4+00	147.7	138.60	9.10		+91.6		# 6822		862 R		12-11-51	
4+38.5	147.8	138.75 out 140.02 in	9.05 7.78	4+38.5	Y NORTH		# 6821		862 R			
5+00	149.5	140.24	9.26		4+49.5		# 6866		607 E Morris		11-3-53	
5+20.6	150.2	140.32 out 142.00 in	9.88 8.20	5+20.6	Y WEST		# 6865		602 E Morris		11-3-53	
					5+32.5		# 6820		856 R Lexington		6-10-51	
					4" PVC 40' 80' 4" 5" SDP 17	5+83.4	# 6819		848 R Lexington		8-18-52	
6+00	151.8	142.32	9.48		6+57.9		# 6818		840 R Lexington		12-11-51	
7+00	153.4	142.72	10.68		7+78.0							
7+64.6	154.6	142.98 out 144.33 in	11.62 10.27	7+64.6	7+78.0		2001-01685		814 R R see next		7-10-01	
8+00	155.1	144.47	10.63		8+83.9		# 7027		808 R Lexington		10-24-94	
9+00	157.2	144.87	12.33		9+48.7		# 7025		802 R Lexington		1-12-52	
9+48.7	157.9	145.07	12.83	9+48.7	9+54.8		# 2003-01204		802 R Lexington		5-6-92	
10+00	158.2	145.27	12.93		10+20.7		# 7026					
11+00	158.6	145.67	12.93		11+69		96-7448		602 E R		5-20-51	
11+50.6	158.4	145.88	12.52	11+50.6	11+69	11+66.0	# 5370	# 5344	729 Waverly		7-26-51	7-26-51
12+00	158.7	146.07	12.63		12+30.9	12+27.9	# 5365	# 4386	723 Waverly		3-28-53	3-9-53
					12+91.8	+88.8	# 5342	# 76	717 Waverly		4-9-51	2-15-52
13+00	159.3	146.47	12.83		13+46.9	13+43.9	# 5341	# 75	708 Waverly		7-26-51	2-15-52
						+97.6	# 74		701 Waverly		2-15-52	
14+00	159.2	146.87	12.33		14+12.7		# 5340		702 Lexington		7-26-51	
14+23.6	159.0	146.97 out 147.88 in	12.03 11.12	14+23.6	14+52.8		# 73		669 Waverly		2-15-52	
					14+59.0		# 4804		676 Lexington		5-31-51	
15+00	159.0	148.18	10.82		15+07.6		# 72		663 Waverly		2-15-52	
					15+23.4		# 4763		670 Lexington		5-28-51	
					15+63.7		# 71		657 Waverly		2-15-52	
					15+88.9		# 4762		664 Lexington		5-28-51	
16+00	160.0	148.58	11.42		16+22.7		# 70		651 Waverly		2-15-52	
					16+46.9		# 4761		658 Lexington		5-28-51	
					16+74.6		# 69		645 Waverly		2-15-52	
16+93.5	160.6	148.96	11.64	16+93.5	17+02.0		# 4760		652 Lexington		5-28-51	
17+00	160.6				+50.8		# 4759		646 Lexington		5-28-51	
					17+62.4		# 68		639 Waverly		2-15-52	
18+00	160.8	149.35	11.45		18+03.1		# 4758		640 Lexington		5-28-51	
					18+33.8		# 67		633 Waverly		2-15-52	
18+45.4	161.6	149.67 out 150.00 in	11.93 11.60	18+45.4	18+53.4		# 4757		634 Lexington		5-28-51	
19+00	161.5	150.21	11.29		19+08.0		# 4179	# 66	628 Waverly		3-22-51	2-15-52
					+67.9		# 4178	# 65	621 R see next		6-1-01	2-15-52
					19+05.0		# 4177	# 65	618 Waverly		3-22-51	3-25-52
20+00	162.9	150.61	12.29		20+30.3	20+27.3	# 4176	# 349	615 Waverly		3-22-51	4-13-53
					+85.9	+82.9	# 4176	# 4790	607 Waverly		3-22-51	12-28-53
21+00	163.0	151.01	11.99		21+57.3	21+54.3	# 7267		603 Waverly			
21+83.5	163.7	151.35	12.35	21+83.5								
					Y NORTH	Y SOUTH						
0+00	157.8	146.80	11.00	0+00 = 3+48.7 in Line #3	0+08.1		# 7033		603 E Morris		1-11-52	
					0+63.3		# 7318		604 E Morris		11-20-54	
1+00	156.3	147.20	9.10		1+02.5		# 7476		609 E Morris		1-28-52	
					+55.1	1+58.1	# 7477		605 E Morris		2-9-52	12-28-51
1+97.4	155.1	147.59	7.51	1+97.4			# 01531		601 E Morris		2-9-52	2-1-53
2+00					2+05.9		# 1040		602 E Morris		4-29-52	8-27-52
					+68.8		# 1041		603 E Morris		4-29-52	11-3-53
					2+08.9		# 6867		602 E Morris			
					+71.8		# 6868		602 E Morris			

#3

#3-A

96-3177 1-896 6022 E MORRIS -

C 47453-6004 E, Morris - 11-20-74 - El Hanny (See S.O. above on line 3A) (8+53.6)

590 - Tap - 859 Fabrique - 4-12-54 - Reynolds Pkg. Co. Inc. - see Pl. G p. 63 (line 6)

472 - Tap - 871 Fabrique - 3-30-54 - Reynolds Pkg. Co. Inc. (Wye 2+81.2)

4764 - Tap - 604 Lexington - 5-28-51 - Frederick Pkg. Co.

7028 - Tap - 820 Lexington - 1-12-52 - Harley Rapp (8+39.6)

6864 - Tap - 6015 E. Morris - 11-3-53 - C. R. Leidy

7485 - Tap - 889 Fabrique - 2-1-54 - Eugene Reynolds (1+16) TV log shows Tap @ 1475.5

7486 - Tap - 877 Fabrique - 2-1-54 - Eugene Reynolds Seal off C 49009 4-14-75 - See new Tap (2+23.4)

350 - Tap - 883 Fabrique - 3-15-54 - Reynolds Pkg. Co. Inc. (Wye is 6' No. of So. Prop. Line) TV log shows Wye E. @ 2+25.5

351 - Tap - 865 Fabrique - 3-15-54 - Reynolds Pkg. Co. Inc. TV log shows Tap @ 3+42.5