

CONSTRUCTION RECORD


SERVICE RECORD

STATION	ELEVATION		Depth	MANHOLE	4-INCH "Y" BRANCHES		No. of Permit		House Number		DATE OF PERMITS			
	Ground	Grade			North West	South East	North West	South East	North West	South East	North West	South East	North West	South East
LINE # 9	0+0	96.9	90.19	6.7	0+00 = 1+27.5 Line # 8	0+22.0	0+19.0	5830	6286	3107 W 3015 S 3110 S	3103 S Bennett 3109 S Bennett	12-9-57	3-4-58	
	1+0	96.7	90.40	6.3		0+82.3	0+79.3	5878	6287	3110 S Everett	3109 S Bennett	12-18-57	3-4-58	
	2+0					1+43.8	1+40.8	6120	6979	3116 S Everett	3115 S Bennett	1-13-58	5-20-58	
						1+95.3	1+92.3	6119	6980	3116 S Everett	3121 S Bennett	1-13-58	5-20-58	
	2+0	96.6	90.60	6.0	2+00.8									
						2+61.0	2+58.0	5879	1417	3128 S Everett	3127 S Bennett	12-18-57	7-4-58 7-18-58	
	3+0	96.8	90.80	6.0										
						3+21.8	3+18.8	6812	9077	3124 S Everett	3133 S Bennett	5-7-58	1-28-59	
						3+82.1	3+79.1	7385	9078	3140 S Everett	3139 S Bennett	6-30-58	1-28-59	
	4+0	96.5	91.00	5.5										
	96.5	91.00	5.5	4+00.3										
5+0	96.3	91.20	5.1		4+44.8	4+41.8	9454	9079	3146 S Everett	3145 S Bennett	7-17-58	1-28-59		
					5+03.8	5+00.8	6014	11927	3152 S Everett	3151 S Bennett	1-7-58	9-10-59		
					5+63.3	5+60.3	5563	23922	3157 S Everett	3156 S Bennett	11-5-57	8-8-59 8-3-59		
6+0	96.6	91.40	5.2											
	96.3	91.48	4.8	6+40.1										
LINE # 10	0+0	96.9	90.30	6.6	0+00 = 1+27.5 Line # 8									
	1+0	97.1	90.70	6.4		0+71.0	0+68.0							
						1+29.6	1+25.6	9085	12077	3076 S Everett	3075 S Bennett	1-29-59	12-21-59	
						1+91.9	1+88.9	8942	13939	3070 S Everett	3069 S Bennett	12-22-58	3-8-61	
	2+0	97.3	91.10	6.2		2+52.7	2+49.7	8170	13845	3064 S Everett	3063 S Bennett	12-30-58	8-29-60	
	3+0	97.4	91.50	5.9	3+00	3+15.9	3+12.9	2000-00095	13946	3054 S Everett	3053 S Bennett	1-14-60	2-9-61	
						3+76.0	3+73.0	8476	13962	3052 S Everett	3051 S Bennett	10-6-58	3-13-61	
	4+0	97.5	91.90	5.6		4+37.5	4+34.5	8415	13527	3046 S Everett	3045 S Bennett	10-21-58	12-5-60	
							4+94.6		13638	3039 S Everett	3038 S Bennett		11-21-60	
	5+0	97.6	92.30	5.3		5+03.9		8578		3040 S Everett	3039 S Bennett	11-7-58		
						5+54.8		13961	3033 S Everett	3032 S Bennett	11-7-58	3-13-61		
6+0	97.6	92.70	4.9	6+00		6+15.3		93-13127	3027 S Everett	3027 S Bennett		7-21-60		
					6+27.5	6+25.8	8576	13340	3028 S Everett	3027 S Bennett	11-7-58	9-20-60		
					6+91.0		7908		3027 S Everett	3026 S Bennett	8-20-58			
7+0	97.5	93.10	4.4		7+36.9		938578-7	13359	3016 S Everett	3015 S Bennett		10-22-60		
					7+54.7	7+52.8	7907		3009 S Everett	3008 S Bennett	8-20-58	7-20-60		
					7+96.8		13152		3009 S Everett	3008 S Bennett		8-5-60		
8+0	97.6	93.50	4.1		8+15.8	8+14.0	7906		3004 S Everett	2103 S 2982 S	8-20-58	8-5-60		
					8+79.0		7905		3004 S Everett	2103 S 2982 S	8-20-58	8-5-60		
	97.7	93.86	3.8	8+89.0										
LINE # 11	0+0	97.3	89.72	7.6	0+00 = 4+60.0 in Line # 8 Exist'g MH	0+32.0	0+29.0	18769		3104 S Everett	3103 S Bennett	7-28-57	4-7-59	
						0+89.8	0+86.8	9678	1829	3110 S Everett	3109 S Bennett	3-3-59	6-25-57	
	1+0	95.9	90.12	5.8		1+50.6	1+47.6	9968	3549	3116 S Everett	3115 S Bennett	4-7-59	1-23-57	
		95.3	90.52	4.8	1+99.6									
						2+08.0	2+05.0	9680	5008	3120 S Everett	3121 S Bennett	4-7-59	1-22-57	
						2+72.0	2+69.0	9454	3601	3128 S Everett	3127 S Bennett	3-3-59	1-23-57	
	3+0	95.4	90.92	4.5		3+32.9	3+29.9	9537	3836	3134 S Everett	3133 S Bennett	3-24-55	2-18-57	
						3+93.8	3+90.8	9970	3602	3140 S Everett	3139 S Bennett	1-7-59	1-23-57	
	4+0	95.2	91.32	3.9	4+00.9									
						4+49.0	4+46.0	8148	3837	3146 S Everett	3145 S Bennett	5-16-53	2-18-57	
5+0	95.5	91.72	3.8		5+12.0	5+09.0	14016	3603	3152 S Everett	3151 S Bennett	3-3-59	1-23-57		
					5+71.9	5+68.9	1451	3139	3159 S Everett	3158 S Bennett	3-3-59	11-23-57		
6+0	95.0	92.12	2.9		6+29.4	6+26.4	7287	1167	3220 S Everett	3219 S Bennett	7-8-58	7-31-57		
	94.9	92.28	2.6	6+41.2										

5088 - Top - 2104 W 31st St - Reynolds - 4-4-57 (6+13.2) 18770-3104 S. St. Clair - 7-28-57 (Top 0+93.9)
 11579 Top 3081 S Bennett Henning 10-9-59 1+03
 3015 S. Bennett (492-38578-7) 10-22-92 (Replaced to existing wye 152 ft south of M.H. 8+89.0 (Top 7+37.0)
 *B 2000-00095-3058 S EVERETT - BOWERS PLB - REPLACED ALL BUT LOWER. 1" - NO ALLEY - 1/14/60



11/11/11



1. The first part of the document discusses the importance of maintaining accurate records. It highlights the need for consistency and attention to detail in all entries.

2. The second section covers the various methods used to collect and analyze data. It includes a detailed description of the experimental procedures and the tools used for measurement.

3. The results of the study are presented in the following tables and graphs. Each data point is carefully documented to ensure the reliability of the findings.

4. The final part of the report provides a comprehensive analysis of the results. It discusses the implications of the data and compares the findings with previous research in the field.

5. In conclusion, the study has provided valuable insights into the subject matter. The data suggests that there is a strong correlation between the variables being studied, which supports the initial hypothesis.